

SPEEDWERKZ PRIVATE LIMITED

Bartley Biz Centre 13 Kaki Bukit Road 4 #01-20 Singapore 417807

Tel: 9619 5936 / Email: info@speedwerk.biz

VEHICLE NO: SGY1387M

MAKE & MODEL: HONDA STREAM

DOA: 26.03.2022

CLAIM TYPE: TP CLAIM

ESTIMATION QUOTE

PARTS	QTY	PRICE (\$)	REMARKS
REAR BUMPER	1	\$ 889.00	Car 689
REAR BUMPER RETAINER LH	1	\$ 67.00	nec
REAR BUMPER RETAINER RH	1	\$ 67.00	nec
TAILGATE	1	\$ 1,534.00	DI 991
TAILGATE ABSORBER LH	1	\$ 198.00	Xsuc
TAILGATE ABSORBER RH	1	\$ 198.00	Xsuc
TAILGATE WEATHERSTRIP	1	\$ 119.00	Det
TAILGATE INNER TRIM	1	\$ 372.00	Car 288.2
TAILGATE EMBLEM LOGO	1	\$ 56.00	nec
TAILGATE EMBLEM	1	\$ 78.00	nec
TAILLAMP LH	1	\$ 451.00	Xsuc
TAILLAMP RH	1	\$ 451.00	Xsuc
END PANEL	1	\$ 564.00	Xr
END PANEL TOP GARNISH	1	\$ 139.00	Xsuc
SPARE TYRE HOLDER	1	\$ 175.00	Xr
TAILGATE GLASS MOULDING	1	\$ 175.00	nec

700/0 LESS 25% X
SUB TOTAL \$ 4,149.75

2530.2
2024.16

SPECIAL NETT ITEMS	QTY	PRICE (\$)	REMARKS
REAR BUMPER CLIPS	1 SET	\$ 40.00	20 nec
REAR TAILGATE INNER TRIM CLIP	1 SET	\$ 30.00	20 nec
WINDSCREEN SEALANT	1	\$ 100.00	50
JOINT SEALANT	1	\$ 100.00	XNN
REAR NUMBER PLATE	1	\$ 100.00	Xsuc
REAR REVERSE SENSOR	1 SET	\$ 350.00	Car 700
SUB TOTAL		\$ 720.00	

LABOUR	QTY	PRICE (\$)	REMARKS
TO DISMANTLE/RENEW THE ACCIDENT DAMAGED PORTION. TO PANEL BEAT, RESHAPE, STRAIGHTEN, ORIENTATE AND ALIGN REPAIR/REPLACEMENT PARTS	1	\$ 1,400.00	600
TO DISCONNECT WIRE HARNESS OF ELECTRICAL COMPONENT TO FACILITATE REPAIRS, RECONNECT AND CHECK FUNCTIONS	1	\$ 80.00	30

TO REMOVE AND RENEW REAR REVERSE SENSOR	1	\$ 120.00	30
TO REMOVE AND REFIT REAR WINDSCREEN	1	\$ 120.00	/
REMOVE AND STRAIGHTEN REAR EXHAUST	1	\$ 150.00	70 LR
TRANSFER PARTS, ATTACHMENT FROM OD TAILGATE TO NEW	1	\$ 200.00	50
TO REMOVE, REFIT REAR LINING TRIM AND GARNISH	1	\$ 200.00	50
SUPPLY SPRAY PAINT MATERIAL AND NECESSARY ITEMS TO RESPRAY BOOTLID, REAR BUMPER, REAR END PANEL AND OTHER AFFECTED AREAS.	1	\$ 1,400.00	600

SUB TOTAL \$ 3,670.00

GRAND TOTAL \$ 8,539.75

3864.16
- 20%
= 3091
= 3100

Thuan @ Lthay to. lom

82235769

4/5 repair 30/3/2022

in 5 days up 1630

F: 3100
RD: 5

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: