

ASSIGNMENT



Pte Ltd

TeamWork Garage Pte Ltd

53 Ubi Avenue 1 #01-23/24 Spore 408934

Paya Ubi Industrial Park

Tel : 6844 2475

E-mail : claims@teamworkgarage.com

ROC number : 201015366H

REPAIR PERFORMA INVOICE

FCI

Vehicle number	SMF696G
Make / Model	MERCEDES E250
Chassis number	WDD2120362B309725
Accident date	25-3-22
Reference	2203-24

Qty	Particulars	Unit Price - SGD \$
<u>PARTS REPLACEMENT - LIST ITEMS</u>		
1	REAR BUMPER	1900 1650 2312.20 / Cut
1	REAR BUMPER DIFFUSAL	385.00 / Scr
1	REAR BUMPER DIFFUSAL CHROME	392.30 399.30 / Scr
2	REAR BUMPER RETAINER	101.20 X Scr
2	REAR BUMPER PDC SENSOR	500 675.40 / Cut
1	REAR BUMPER INNER GUIDE	255.20 / X Scr
1	REAR BUMPER REINFORCEMENT	1124.20 1124.20 / DT
1	REAR EXHAUST SILENCER	1779.80 / Xr
1	REAR EXHAUST SILENCER CHROME TIP	399.30 Xr
		7431.60
	Less 10 %	743.16
	Subtotal	6688.44
	Balance C/F	6688.44
<u>PARTS REPLACEMENT - SPECIAL NETT</u>		
1 SET	REAR BUMPER CLIP	30.00 / Nec
	Subtotal	6718.44
<u>LABOUR AND MISCELLANEOUS CHARGES</u>		
1	CHECK WIRING & LIGHTING SYSTEM	60.00 30
2	REMOVE & REPLACE REAR PDC SENSOR	150.00 40
3	REMOVE & REFIT TRIMS & GARNISHES FOR REPAIR	150.00 XNN
4	PANEL BEATING ON AFFECTED AREAS	800.00 300
5	SPRAY PAINTING ON AFFECTED AREAS	800.00 200
	Subtotal	1960.00
	Grandtotal	8678.44

HK Auto Cons... notice
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

3521
3550

Thevan@lthh auto. low

82235769

29/3/22 1400

L/S ~~for~~ after repair photo

3clay swp