



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                       |  |   |                            |                    |
|---|--|---|----------------------------|--------------------|
| MS FIRST CAPITAL INSURANCE LTD<br>36 ROBINSON ROAD<br>#16-01 CITY HOUSESINGAPORE 068877 |  |   | Ref: CS/FCI22002840/Vqy3e2 |                    |
|   |  |   | Date: 24/06/2022           |                    |
|   |  |   | Code: FCI2                 |                    |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                       |  |   |                            |                    |
|   | Insured Veh.   | SH 4880H  | Veh. Inspected             | SMF 696G           |
|   | Policy No.   |   | Coverage (\$)              | 0.00               |
|   | Claim No.  | D220000896MSH   | Excess (\$)                | 0.00               |
|   | Assign From  | AINI BINTE  | Assign Date                | 28/03/2022         |
| <b>2. Vehicle Particulars &amp; Condition</b>   |  |   |                            |                    |
|   | Make & Model   | MERCEDES BENZ E250  | c.c                        | 1991               |
|   | Engine No.   | HIDDEN  | Year of Reg.               | 2016               |
|   | Chassis No.  | WDD2120362B309725   | Colour                     | GREY               |
|   | Odometer   | 91613 KM  | Steering                   | IN ORDER           |
|   | Brakes   | IN ORDER  | Modification               | STANDARD ALLOY RIM |
|   | General  | GOOD  |                            |                    |
| <b>3. Conditions of Tyres</b>   |  |   |                            |                    |
|   |  | Size  | Make                       | Balance            |
|   | R/H Front Tyre   | 245/40 R18  | BRIDGESTONE                | 6 mm               |
|   | L/H Front Tyre   | 245/40 R18  | BRIDGESTONE                | 6 mm               |
|   | R/H Rear Tyre  | 245/40 R18  | BRIDGESTONE                | 6 mm               |
|   | L/H Rear Tyre  | 245/40 R18  | BRIDGESTONE                | 6 mm               |
| <b>4. Description of Damages</b>  |  |   |                            |                    |
|   | THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.<br>DAMAGES SEE DETAILS.   |   |                            |                    |
| <b>5. General Information</b>   |  |   |                            |                    |
|   | Accident Date  | 25/03/2022  | Inspection Date            | 29/03/2022         |
|   | Survey held at   | TEAMWORK GARAGE PTE LTD<br>53 UBI AVENUE 1<br>#01-24<br>SINGAPORE 408934. |                            |                    |
| <b>5a. Remarks</b>  |  |   |                            |                    |
|   | A)DAMAGES CONSISTENT TO ACCIDENT REPORT.<br>B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |   |                            |                    |
| <b>5b. Estimate Days of Repair</b>  |  |   |                            |                    |
|   | ESTIMATED NORMAL PERIOD FOR REPAIR:  |   | 3 Working Days             |                    |