

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Part prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

FONG MOTORS

1 Kaki Bukit Ave 6 #01-27/45

AutoBay@ Kaki Bukit, Singapore 417883

Tel: 6748 5648, Email: fongmotors@gmail.com

TP Sampo Denise

Estimate of Cost of Repairs

Date 24-Apr-2022

Vehicle No. SJT7534M SJY7534M

Model Toyota Wish

CHASSIS/ENG# 26E200009192

PARTS

S/N	Item	Quantity	Unit Price	Amount
1	Bonnet <i>Dented</i>	1	\$868.80	\$868.80 ✓
2	Bonnet Hinge <i>3 x 14</i>	2	\$51.10	\$102.20 X
3	Bonnet Sponge <i>1 on</i>	1	\$390.50	\$390.50 X
4	Bonnet Emblem <i>new</i>	1	\$58.50	\$58.50 ✓
5	Head Lamp <i>cracked</i>	2	\$863.60	\$1,727.20 ✓
6	Radiator Grille <i>Deformed & Cracked</i>	1	\$292.80	\$292.80 ✓
7	Top Panel Garnish <i>Deformed</i>	1	\$115.70	\$115.70 ✓
8	Front Bumper <i>Deformed</i>	1	\$679.40	\$679.40 ✓ 584
9	Bumper Side Retainer <i>new</i>	2	\$55.30	\$110.60 X.
10	Bumper Bracket <i>new</i>	2	\$42.90	\$85.80 X.
11	LH Bumper Lower Grille Complete <i>Deformed</i>	1	\$167.30	\$167.30 ✓
12	Brace Panel <i>new</i>	1	\$89.70	\$89.70 X
			Sub-total 1	\$4,688.50

3817.30
2860.72

NETT ITEMS

S/N	Item	Quantity	Unit Price	Amount
1	Front Number Plate <i>new</i>	1	\$40.00	\$40.00 X
			Sub-total 2	\$40.00

LABOUR

1	To knock and repair affected areas		\$800.00	400
2	To conduct wiring checks		\$80.00	30
3	Spray painting on all affected parts		\$800.00	400
			Labour Total	\$1,680.00

830

Parts & Labour Total \$6,408.50

30(SN)

Supplementary

1 set clip bumper

new

60.00/SN

total: 3720.72

04 Days w/s: 2.9K