



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD		Ref: CS3/CTI22002843/Vqy3	
3 ANSON ROAD #16-00		Date: 28/03/2022	
SPRINGLEAF TOWERSINGAPORE 079909		Code: CTI	
<b>1. Policy Particulars :- (THIRD PARTY CLAIM)</b>			
Insured Veh.	GBL 6298G	Veh. Inspected	SMH 4705C
Policy No.	DMCVSNW00154122100	Coverage (\$)	0.00
Claim No.	SNM22D202088/C02/GBL6298 G/TANKW	Excess (\$)	0.00
Assign From	TAN KIAN WEI BILLY	Assign Date	28/03/2022
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
<b>4. Description of Damages</b>			
<b>5. General Information</b>			
Accident Date	25/03/2022	Inspection Date	05/04/2022
Survey held at	SYNERGY @KB #05-66		
Repairer	TRIPLE-T AUTOMOBILE		
<b>5a. Remarks</b>			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.			