

ESTIMATE

Company Reg No. 200609327M
 GST Reg No. MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
CYCLE & CARRIAGE LEASING PTE LTD 239 ALEXANDRA ROAD SINGAPORE 159930 Contact No Mobile: 85188668	Cust No/Name / CYCLE & CARRIAGE LEASING PTE L Reg No/Reg Date GBL7220Z / 21/02/2022 Date In/Mileage / 0 Chassis No VF7V1ZKXZM2117098 Engine No 105TCM0011028 Make/Model CITCV/ELECTRIC DISPATCH 75KW Colour/Trim WPP BLANC BANQUISE / FX BLACK "FX"

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00073	Cash	26/03/2022/ 13:29	TLE	261 / Edwin Caina	17678

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M SUNDRY NUMBER PLATE TRIM X 98137972XT				
M SUNDRY EMBLEM-DISPATCH X 98345366VD				
M SUNDRY BADGE-e X 98399030RQ				
M SUNDRY DOOR ADHESIVE TAPE X 9845360880				
M SUNDRY SUPPLY 70 KM/H STICKER X nn				120.00
M SUNDRY SUPPLY 6 PAX STICKER X nn				80.00
E PNT88000 RENEW RR BUMPER REPAIR TAILGATE LH / RH				760 3040.00
E PNT98000 RESPRAY TAILGATE LH & RH				760 1100.00 X
A 54900099 CHECK WIRING ELECTRICAL SYSTEM				80.00 /
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM				300.00 /
M SUNDRY SUPPLY RR NUMBER PLATE WITH CASING X nn				80.00
E PNT88000 REMOVE & REFIT REVERSE SENSOR				100.00 /
M SUNDRY SUPPLY C&C BADGE X nn				50.00
M SUNDRY Sundries X nn				50.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
 Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE FRANCE PTE. LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE
 209 Pandan Gardens, Singapore 609339 Tel: (65) 6568 4501 Fax: (65) 6565 1240



ESTIMATE

Company Reg No: 200609327M
 GST Reg No: MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
CYCLE & CARRIAGE LEASING PTE LTD	Cust No/Name / CYCLE & CARRIAGE LEASING PTE L
239 ALEXANDRA ROAD	Reg No/Reg Date GBL 1220Z / 21/02/2022
SINGAPORE 159930	Date In/Mileage / 0
Contact No Mobile: 85188668	Chassis No VF7V1ZKXZMZ117098
	Engine No 105TCM0011028
	Make/Model CITCV/ELECTRIC DISPATCH 75KW
	Colour/Trim WPP BLANC BANQUISE / FX BLACK "FX"

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00073	Cash	26/03/2022/ 13:29	TLE	261 / Edwin Caina	17678

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M REAR BUMPER / BR (take photo new part)	1.00	1023.00	0.00	1023.00
M BUMPER BRACKET	1.00	109.00	0.00	109.00
M BUMPER BRACKET LH LAT	1.00	138.00	0.00	138.00
M BUMPER BRACKET RH LAT	1.00	138.00	0.00	138.00
M BUMPER BRACKET RH LAT	1.00	123.00	0.00	123.00
M BUMPER BRACKET	1.00	605.00	0.00	605.00
M BADGE-LOGO	1.00	58.00	0.00	58.00

Estimate

SURVEYOR NAME: Steve CLKK
 SURVEYOR SIGNATURE: 25/4/22, 19.30pm
 DATE: P/P
 REMARKS: 2 dys
Ry BL sy

Confirm & accepted by

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No legal modification(s) is allowed

Authorized signatory and company stamp

Parts	2,194.00
Labour	4,620.00
Standard Menu	0.00
Specialist Job	0.00
Diagnostics Job	0.00
Sundry/Others	380.00
Total (w/o GST)	7,194.00

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.