



ACE AUTOLUTION PTE LTD

13 Kaki Bukit Road 4 Bartley Biz Centre #03-29
Singapore 417807

Tel: 6702 4282 Fax: 6702 4202

TP Budget Direct
Xiao Chen

March 22

Page No. 1

Vehicle No. SMY6361H BMW 116D

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(S\$)		SURVEYOR ADJUSTMENT		
PARTS (LIST ITEMS)							
1	REAR BUMPER <i>Repis</i>	<i>new</i>		1141.00	<i>+</i>	<i>628</i> <i>59680</i>	
1	REAR BUMPER TOWING COVER <i>new</i>			72.00	<i>+</i>		
2	REAR BUMPER REFLECTOR LH & RH @\$74.20 <i>new</i>			148.40	<i>+</i>		
1	REAR BUMPER LOWER GUARD <i>new</i>			196.00	<i>+</i>		
1	REAR BUMPER LOWER GUARD COVER <i>new</i>			778.00	<i>+</i>		
2	REAR BUMPER SIDE BRACKET 2PCS <i>new</i>			35.40	<i>+</i>		
1	REAR FENDER RH <i>Repis</i>			2760.00	<i>+</i>		
1	REAR FENDER GARNISH RH <i>Repis</i>			220.00	<i>+</i>		
1	REAR FENDER INNER SHIELD RH <i>new</i>			210.00	<i>+</i>		
1	REAR SHOCK ABSORBER RH <i>new</i>			772.00	<i>+</i>		
1	REAR LOWER ARM RH <i>new</i>			860.00	<i>+</i>		
1	REAR KNUCKLE ARM RH <i>new</i>			1160.00	<i>+</i>		
1	REAR DOOR LOWER SKIRT <i>new</i>			628.00	<i>✓</i>		
				8980.80			
			less	5%	5%		
				449.04			
				8531.76			
SPECIAL NETT ITEMS							
1 SET	REAR BUMPER CLIPS <i>new</i>	<i>new</i>		100.00	<i>+</i>	<i>850</i>	
1 SET	REVERSE SENSOR <i>new</i>			550.00	<i>+</i>		
1	REAR RIM RH <i>at</i>			<i>1300</i>	<i>✓</i>		
1	REAR TYRE RH <i>new</i>			380.00	<i>+</i>		
1 SET	REAR FENDER INNER SHEILD CLIPS <i>new</i>			100.00	<i>+</i>		
Total Parts				10271.76			



ACE AUTOLUTION PTE LTD
 13 Kaki Bukit Road 4 Bartley Biz Centre #03-29
 Singapore 417807
 Tel:6702 4282 Fax:6702 4202

Page No. 2

Vehicle No. SMY6361H BMW 116D

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	OUR ASSESSMENT
	LABOUR		
1	To remove the affected parts & fittings to commence repairs and replace damaged parts	1600.00	200.
2	To supply paint materials, expandable items & putty, respray paint on parts replaced	1400.00	700
3	To remove , fefix wiring system at accident damage areas and check for proper function	150.00	X
4	To perform anti-rust treatment on affected areas	100.00	X
5	To conduct water seepage test	150.00	X
6	To remove rear boot mechanism	150.00	X
7	To remove and replace underecarriage part	210.00	X
8	To conduct wheel alignment test	150.00	200
9	To clear fault code with diagnostic computer and reset to specification .	180.00	X
Labour Total :		4090.00	
TOTAL (PARTS & LABOUR):		14361.76	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

total: 2426.60

L/S: 1.9K ✓

03 Days.

980