



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SKM8026A

Wong Ching Heng

Blk 409 Woodlands Street 41
#12-99
Singapore 730409

Vehicle & Document Information

WIP No 55753
Reg No/Reg Date SKM8026A / 17/01/2022
Date In/Mileage 0
Chassis No W1K2130532B0091318
Engine No 27492032001110
Make/Model MB/E 300 e SEDAN
Colour/Trim 028 831 Graphite Gr/ 042 214 Rough Leath

Account No	Terms	Date/Time Printed	CSE	Operator	Description of Goods / Services	Qty	Unit Price	Disc%	Amount
WCV47510	CRDVCH	24/03/2022/ 09:20	YK	395 / Yik Chan Hoe					

Z REQUEST

Customer Request
M BPNSUN

POLICY NO/ACC DATE : 7220003847 // 23/03/2022
DRIVE IN/EXCESS : 23/03/2022 // TP VEH NO YQ4321L CHINA TAIPING
DATE IN/DATE SURVEY:
BY/AUTHORIZED ON :

A BPILAB

PANEL BEATING TO REPAIR AFFECTED AREAS, REMOVE AND REPLACE WITH NEW BODY PANELS WITH REFINISH

A BPIRES

RESPRAY BONNET AND FRONT BUMPER

A BPILAB

USING XENTRY SYSTEM TO CHECK CONTROL UNITS, RESET SYSTEM TO STANDARD SETTINGS. NETT

A BPILAB

CHECK HEADLAMP WITH FOCUS ADJUSTMENT. NETT

M LEFT HEADLAMP UNIT

M FRONT BUMPER

M FRONT AIR DUCT SEGMENT

M FRONT BUMPER LOWER CHROME TRIM

M LEFT FRONT BASIC CARRIER FOR BUMPER

1.00	3538.41	00.00	3538.41
1.00	1600.95	00.00	1600.95
1.00	141.17	00.00	141.17
1.00	188.52	00.00	188.52
1.00	68.83	00.00	68.83

960, 1200.00

1600, 2400.00

0.10 380.00

120.00

Stark (LKK)
10/5/22, 3:30p

WL AL
5 hrs
PIP

MY BL sy

Yik Chan Hoe

Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center

DDD: 6771 4353 HP: 9186 5109 Fax: 6872 1272

Email: chanhoe.yik@cyclecarrage.com.sg

Confirmed & accepted by

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting

Authorized signatory and company stamp

7% GST on	Nett	9,637.88
	9637.88	674.65

Total Payable 10,312.53

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Acknowledged by Repairer

Signature:

Date:

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



and Mercedes-Benz are trademarks of Mercedes-Benz Group AG