

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLR 6737G

| Qty | Description of Parts | Condition | Estimate By Workshop (\$)) | Our Adjusted (\$) |
|-----|--|---------------|-------------------------------|-------------------|
| | REPLACEMENT OF PARTS | | | |
| 1 | SEAL,HOOD TO FR END (SN) | NECESSARY | 54.70 | 54.70 |
| 4 | PIECE,RR BUMPER (SN) | NECESSARY | 17.20 | 17.20 |
| 1 | SUPPORT,FR BUMPER (SN) | NOT NECESSARY | 84.70 | - |
| 1 | SUPPORT,FR BUMPER (SN) | NOT NECESSARY | 84.70 | - |
| 1 | COVER,FR BUMPER (SN) | BROKEN | 547.10 | 547.10 |
| 1 | BRACKET,FR BUMPER (SN) | BROKEN | 109.80 | 109.80 |
| 1 | COVER,FR BUMPER (SN) | NOT NECESSARY | 31.10 | - |
| 1 | COVER,FR BUMPER (SN) | NOT NECESSARY | 31.10 | - |
| 1 | GRILLE,RADIATOR (SN) | CRUSHED | 180.30 | 180.30 |
| 1 | COVER ASSY,ENGINE (SN) | NOT NECESSARY | 197.00 | - |
| 1 | ABSORBER,FR BUMPER (SN) | NOT NECESSARY | 84.20 | - |
| 1 | REINFORCEMENT (SN) | NOT NECESSARY | 758.70 | - |
| 1 | GRILLE SUB-ASSY (SN) | CRUSHED | 367.20 | 367.20 |
| 1 | EMBLEM ASSY (SN) | CUT | 96.60 | 96.60 |
| 1 | LAMP ASSY,FOG,RH (SN) | NOT NECESSARY | 1,009.10 | - |
| 1 | LAMP ASSY,FOG,LH (SN) | NOT NECESSARY | 1,009.10 | - |
| 1 | UNIT,HEADLAMP (SN) | NOT NECESSARY | 2,794.80 | - |
| 1 | UNIT,HEADLAMP (SN) | NOT NECESSARY | 2,794.80 | - |
| 1 | SUNDRIES (SN) | NECESSARY | 100.00 | 50.00 |
| 1 | REGN PLATE (PO#)(SN) | BROKEN | 80.00 | 80.00 |
| | | | 10,432.20 | 1,502.90 |
| | <u>LABOUR</u> | | | |
| | REPLACE ACC AFF PARST AND PANEL STRAIGHTEN AND REALLIGN ACC AFF AREA. | | 1,440.00 | 720.00 |
| | RESPRAY ACC AFF AREA. | | 1,180.00 | 590.00 |
| | RESET ECU UPON COMPLETION OF REPAIR. | | 180.00 | 180.00 |
| | | | 2,800.00 | 1,490.00 |
| | GRAND TOTAL | | 13,232.20 | 2,992.90 |

Report Ref No. CS/SMR22002851/Eqy3n2



Page No.:2 of 2

RECOMMENDED COST OF REPAIRS 2,992.90

Report Ref No. CS/SMR22002851/Eqy3n2



Automotive Assessor



ANG BRYAN TANI

Automotive Assessor / Investigator