

## Vehicle Damage Assessment Report for [SGZ6937M]

Estimate Created: 03/04/2022 13:07 by LKK\_admin-a  
(LKK\_Auto\_Consultants\_Pte\_Ltd)

Owned: 22/07/2022 09:41 by LKK\_cs-a (LKK\_Auto\_Consultants\_Pte\_Ltd)

### **General Information**

---

Insurance Company	III	Claim Number
Claim Type	TP	
Workshop	LKK_Auto_Consultants_Pte_Ltd	Reference Number

### **Vehicle Information**

---

Brand	Toyota	Model	Corolla
Engine Type			
License Plate Number	SGZ6937M	VIN (or Chassis #)	

### **Vehicle Condition**

---

Damaged Diagram	Odometer	243,391.00 Km
	Tyres Condition	
	Front Left	mm
	Front Right	mm
	Rear Left	mm
	Rear Right	mm

### **Comments**

---

- Recommended cost of repair at lump sum : \$4350.00 with 9 days for repair Insurlogic 1 (22/07/2022 09:38)

**Parts**

Description	Number/Type	Qty	Cost	Markup/Disc.%	Sum
REAR BUMPER		1	485.00	-25.00 %	363.75
REAR BUMPER RETAINER		1	70.00	-25.00 %	52.50
REAR TAIL LAMPS		1	642.00	-25.00 %	481.50
REAR BOOT COVER		1	874.40	-25.00 %	655.80
REAR BOOT WEATHERSTRIP		1	124.40	-25.00 %	93.30
REAR BOOT EMBLEM		1	61.50	-25.00 %	46.13
REAR BOOT AXIO EMBLEM		1	61.70	-25.00 %	46.28
REAR BOOT X EMBLEM		1	67.70	-25.00 %	50.78
REAR BOOT LOCK UPPER		1	191.60	-25.00 %	143.70
FRONT BUMPER		1	485.00	-25.00 %	363.75
FRONT GRILLE		1	347.00	-25.00 %	260.25
FRONT GRILLE EMBLEM		1	71.70	-25.00 %	53.78
END PANEL		1	481.90	-25.00 %	361.43

Parts Subtotal 2,972.95

**Materials**

Description	Number/Type	Qty	Cost	Markup/Disc.%	Sum
REAR BUMPER CLIPS		1.0	30.00	0.00 %	30.00
REAR BUMPER SCREW CLIPS		1.0	20.00	0.00 %	20.00
REVERSE SENSORS		1.0	200.00	0.00 %	200.00
END PANEL INNER TRIM CLIPS		1.0	16.00	0.00 %	16.00
FRONT BUMPER CLIPS		1.0	30.00	0.00 %	30.00
FRONT GRILLE CLIPS		1.0	18.00	0.00 %	18.00

Materials Subtotal 314.00

**Labor**

## Replace/RnR

Description	Type	Cost	Markup/Disc %	Price
REPLACE FRONT BUMPER	RnR	100.00	0.00 %	100.00
REPLACE REAR BUMPER	RnR	100.00	0.00 %	100.00
REPLACE REAR BOOTLID AND ATTACHMENT	RnR	150.00	0.00 %	150.00

REPLACE END PANEL	RnR	300.00	0.00 %	300.00
CHECK WIRING	RnR	60.00	0.00 %	60.00
ANTI RUST	RnR	80.00	0.00 %	80.00

## Repair

Description	Severity	Cost	Markup/Disc %	Price
REAR FLOOR PANEL	Unknown	350.00	0.00 %	350.00

## Paint

Description	Paint Type	Cost	Markup/Disc %	Price
FRONT BUMPER	Full spray	200.00	0.00 %	200.00
REAR BUMPER	Full spray	200.00	0.00 %	200.00
REAR BOOTLID	Full spray	200.00	0.00 %	200.00
END PANEL	Full spray	200.00	0.00 %	200.00
FLOOR PANEL	Full spray	200.00	0.00 %	200.00

Labor Rate	S\$ 50 / Hour	General Labor Subtotal	1,140.00
		Paint Labor Subtotal	1,000.00
		<b>Labor Subtotal</b>	<b>2,140.00</b>

**Summary**

Repair Cost	5,426.95
Discount(20 %)	(1,076.93)
	4,350.02
Excess	(0.00)
GST(0.00 %)	0.00
<b>Grand Subtotal</b>	<b>4,350.02</b>