

ESTIMATE OF REPAIR

Veh# : SGZ6937M

Accident Date : 27/3/2022

Location : CTE TOWARDS CITY

TP 111
Xiao Tony

Model:

3P.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplemental item(s) must be resurveyed and is subject to approval from Insurance Company

Acknowledged by Repairer

Signature:

S/Nos.	Qty	Description	List \$	LS/Nett \$	Nett \$
1	1pc	Rear bumper <i>Distorted</i>	681.40	✓ 485	
2	10pcs	Rear bumper clips <i>NEW</i>		30.00	✓
3	2pcs	Rear bumper screw clips <i>NEW</i>		20.00	✓
4	2pcs	Rear bumper o/s & n/s reflector <i>NEW</i>	475.40	X	
5	2pcs	Rear bumper o/s & n/s retainer <i>NEW</i>	362.70	70	
6	2pcs	Rear reverse sensor <i>Damaged</i>		280.00	200
7	1pc	Rear end panel <i>Damaged</i>	481.90	✓	
8	1pc	Rear end panel inner trim <i>Damaged</i>	453.80	200	
9	4pcs	Rear end panel inner trim clips <i>NEW</i>		16.00	✓
10	2pcs	Rear o/s & n/s tail lamp <i>Cracked</i>	878.20	642	
11	2pcs	Rear o/s & n/s tail lamp panel <i>NEW</i>	563.80	X	
12	2pcs	Rear o/s & n/s tail lamp sealant <i>NEW</i>	100.00	X	
13	pc	Rear Regn. No. Plate lamp <i>NEW</i>	167.50	X	
14	1pc	Rear boot cover <i>Cracked</i>	874.40	✓	
15	1pc	Rear boot cover weatherstrip <i>NEW</i>	124.40	✓	
16	1pc	Rear boot cover emblem	61.50	✓	
17	1pc	Rear boot cover 'AXIO' emblem <i>NEW</i>	61.70	✓	
18	1pc	Rear boot cover 'X' emblem	67.70	✓	
19	1pc	Rear boot cover inner trim	282.25	X	
20	11pcs	Rear boot cover inner trim clips <i>NEW</i>		33.00	X
21	2pcs	Rear boot cover o/s & n/s hinges <i>NEW</i>	164.50	X	
22	1pc	Rear boot cover moulding <i>NEW</i>	187.10	X	
23	4pcs	Rear boot cover moulding clips <i>NEW</i>		16.00	X
24	1pc	Rear boot cover lock (Upper) <i>Damaged</i>	191.60	✓	
25	1 pc	Front bumper <i>Damaged</i>	796.70	485	
26	10 pcs	Front bumper clips <i>NEW</i>		30.00	✓
27	1 pc	Front bumper insulator <i>NEW</i>	394.20	X	
28	1 pc	Front bumper enforcement <i>NEW</i>	596.70	X	
29	2 pcs	Front bumper o/s & n/s retainer <i>NEW</i>	386.70	X	
30	pc	Front bumper grille (Lower) <i>NEW</i>	496.60	X	
31	1 pc	Front bumper enforcement cover <i>NEW</i>	206.70	X	
32	1 pc	Front grille <i>Cracked</i>	436.70	347	
33	1 pc	Front grille emblem <i>NEW</i>	71.70	✓	
34	6 pcs	Front grille clips <i>NEW</i>		18.00	✓
35	1 pc	Front bonnet <i>NEW</i>	799.70	X	
36	2 pcs	Front o/s & n/s head lamp <i>NEW</i>	896.80	X	
37	1 pc	Front reg. no. plate <i>NEW</i>		45.00	X
38	1 pc	Front reg. no. plate bracket <i>NEW</i>		29.00	X
		Sub Total:	11,262.05	517.00	0.00
			25%	0%	10%
		After Less %:	8,446.54	517.00	0.00
		Labour			
1		To dismantle damaged parts, straighten & welding.		1000.00	1000
2		To spray painting.		1200.00	1000
3		To remove & replace rear exhaust.		100.00	X
4		To re set electrical system.		180.00	60 X
5		To check wiring.		100.00	60
6		To re seal anti rust.		100.00	80
		Sub Total:		3,080.00	
		Total:		12,043.54	
		After Less 20%:		9,634.83	

L/sum Repair
10 repair days

Chan San Choon
Director

Dip (Eng), AAE, MEM, MSAE (Aust)



24 hr accident service



PAYNOW