



ASSESSMENT FOR REPAIR : JOG8893
KAWASAKI EX250-L
COE EXPIRY :

Lump Sum / Part by Part

Qty	Description	Repairer's Estimate	1st Survey	Repair Survey	Final Survey
1	HEAD COWLING	353.00	/ BT		
1	HEADLIGHT	1,391.00	/ mis		
1	HEADLIGHT BRACKET	642.00	/ BT		
1	FRONT FORK (L&R SET)	3,852.00	n.		
1	STEERING STEM	738.00	/ cut		
1	FRONT FENDER	417.00	n.		
1	FRONT RIM	1,766.00	n.		
1	RADIATOR	1,316.00	n.		
1	LH RADIATOR INNER PANEL	193.00	n.		
1	RH RADIATOR INNER PANEL	193.00	n.		
1	INNER FENDER	193.00	n.		
1	L&R HANDLE BAR	449.00	n.		
1	L&R LEVER	161.00	/ Scr		
1	L&R GRIPS	98.00	/ Scr		
1	L&R BAR END	98.00	/ Scr		
1	L&R MIRROR	471.00	/ mis		
1	RECTIFIER	770.00	n.		
1	FRONT L&R SIGNAL LIGHTS	289.00	/ Crq		
1	SPEEDOMETER	1,830.00	/ mis		
1	FRONT LH COWLING	1,284.00	/ Cut		
1	RH ENGINE CASING	385.00	/ Cut		
1	RH RIDER FOOTREST PEG	225.00	/ Scr		
1	RH BRAKE PEDAL	129.00	/ Scr		
1	RH PILLION FOOTREST PEG	118.00	/ Scr		
1	EXHAUST MUFFLER	1,926.00	/ Scr		
1	RH TAIL COWLING	161.00	/ Scr		
1	LH TAIL COWLING	161.00	/ Scr		
1	REAR FENDER	140.00	/ Scr		
1	RER LH SIGNAL LIGHT	129.00	/ Scr		
1	REAR SIGNAL LIGHT BRACKET	128.00	/ Scr		
1	PILLION SEAT	482.00	/ Scr		
1	LH PILLION FOOTREST PEG	118.00	/ Scr		
1	LH RIDER FOOTREST PEG	225.00	/ Scr		
1	LH GEAR PEDAL	118.00	/ Scr		
1	CHAIN	240.00	/ Scr		
1	SPROCKET	260.00	/ Scr		
1	REAR RIM SLIDER	128.00	n.		
1	RH BELLY COWLING	161.00	n.		
1	LH BELLY COWLING	161.00	n.		
1	FUEL TANK	2,087.00	/ Scr		
1	FRONT RH COWLING	1,284.00	/ Scr		

25,270.00

Special Nett Items

STEERING CONE & BEARING
 FRONT FORK ALIGNMENT
 WHEEL ALIGNMENT
 FRAME ALIGNMENT

120.00	/ nue		
220.00	/ SOR		
120.00	/ 36		
200.00	/ 40		

660.00

Total Parts

25,930.00

Labour Charges

1 Workmanship to renew damage parts & areas

480.00
 480.00

200

Total Parts & Labours Concluded

26,410.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Thevan @ LKK Auto. Com
 82235769

29/3/22 1630

L/S sday swp

Not economical to repair
 Submit total cost

SANFU MOTOR PTE LTD

Company Reg No.: 200612487G

1 Kaki Bukit Ave 6, #02-43, AutoBay@Kaki Bukit, Singapore 417883

Direct Line: 9061 3299 Tel: (65) 6744 7753 Fax: (65) 6744 6010

Email: sanfumotor0243@gmail.com

TOTAL