

(08/11/11)

ASS. REC. BY: ThuanREF: C04/11122002857/993**ASSIGNMENT**

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: RMSK

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: 306 8893 Yr Regn: 2014Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: hawasahi EX 250 c.c. 250Colour: green A/C: Insured / Std / NI / NASp. Reading: not avail T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: PNKEX 250LLMCS 7176Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 110/70 R17R: 110/70 R17BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 5 mm R/Bal. 5 mm

L/Bal. _____ mm L/Bal. _____ mm

D.O.A. 30/11/21 D.O.I. 29/3/21 700Survey held at Sanfa motorDes. of Damages: Fit / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>Sum Insured: RMSK</u>

Date/Time, File Pass to?

☐ : Prell. Report

Days Of Repair: _____

1)

☐ : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$ _____) ☐ : S + RS _____ SI☐ : Interview (\$ _____) Photos☐ : Tech. Invs (\$ _____) Others☐ : Weekend (\$ _____) TOTAL

Report Format : _____

Lump Sum / I.B.I: (\$ _____)

Survey Fee:

Transportation:

Photos

Others

TOTAL



ASSESSMENT FOR REPAIR : JQG8893
KAWASAKI EX250-L
COE EXPIRY :

Lump Sum / Part by Part

Qty	Description	Repairer's Estimate	1st Survey	Repair Survey	Final Survey
1	HEAD COWLING	353.00	/RT		
1	HEADLIGHT	1,391.00	/mis		
1	HEADLIGHT BRACKET	642.00	/BT		
1	FRONT FORK (L&R SET)	3,852.00	/n		
1	STEERING STEM	738.00	/cut		
1	FRONT FENDER	417.00	/n		
1	FRONT RIM	1,766.00	/n		
1	RADIATOR	1,316.00	/n		
1	LH RADIATOR INNER PANEL	193.00	/n		
1	RH RADIATOR INNER PANEL	193.00	/n		
1	INNER FENDER	193.00	/n		
1	L&R HANDLE BAR	449.00	/n		
1	L&R LEVER	161.00	/scr		
1	L&R GRIPS	98.00	/scr		
1	L&R BAR END	98.00	/scr		
1	L&R MIRROR	471.00	/mis		
1	RECTIFIER	770.00	/n		
1	FRONT L&R SIGNAL LIGHTS	289.00	/lrg		
1	SPEEDOMETER	1,830.00	/mis		
1	FRONT LH COWLING	1,284.00	/cur		
1	RH ENGINE CASING	385.00	/cur		
1	RH RIDER FOOTREST PEG	225.00	/scr		
1	RH BRAKE PEDAL	129.00	/scr		
1	RH PILLION FOOTREST PEG	118.00	/scr		
1	EXHAUST MUFFLER	1,926.00	/scr		
1	RH TAIL COWLING	161.00	/scr		
1	LH TAIL COWLING	161.00	/scr		
1	REAR FENDER	140.00	/scr		
1	RER LH SIGNAL LIGHT	129.00	/scr		
1	REAR SIGNAL LIGHT BRACKET	128.00	/scr		
1	PILLION SEAT	482.00	/scr		
1	LH PILLION FOOTREST PEG	118.00	/scr		
1	LH RIDER FOOTREST PEG	225.00	/scr		
1	LH GEAR PEDAL	118.00	/scr		
1	CHAIN	240.00	/scr		
1	SPROCKET	260.00	/scr		
1	REAR RIM SLIDER	128.00	/n		
1	RH BELLY COWLING	161.00	/n		
1	LH BELLY COWLING	161.00	/n		
1	FUEL TANK	2,087.00	/scr		
1	FRONT RH COWLING	1,284.00	/scr		

25,270.00

Special Nett Items

STEERING CONE & BEARING	120.00	/nec		
FRONT FORK ALIGNMENT	220.00	/sop		
WHEEL ALIGNMENT	120.00	/sb		
FRAME ALIGNMENT	200.00	/to		

660.00

Total Parts

25,930.00

Labour Charges

1 Workmanship to renew damage parts & areas

480.00

480.00

200

Total Parts & Labours Concluded

26,410.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Thevan @ LKK Auto. Com
82235769
29/3/22 1630
LRS sday swp

SANFU MOTOR PTE LTD

Company Reg No.: 200612487G

1 Kaki Bukit Ave 6, #02-43, AutoBay@Kaki Bukit, Singapore 417883

Direct Line: 9061 3299 Tel: (65) 6744 7753 Fax: (65) 6744 6010

Email: sanfumotor0243@gmail.com