

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/HLA22002866/UQY3E2

Date: 26/04/2022

REFERENCE

Handling Insurer: HL Assurance Pte Ltd Policy No: MP318476
Claimant Vehicle No : FBT3361J Insured Vehicle No : SMC4015L
Date of Loss: 27/03/2022 Nature of Claim: TP Claim No: MPC03269

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBT3361J**
Make & Model: YAMAHA NMAX155, 155cc Engine No: G3L8E0707450
Reg. Date: 11/01/2022 (Man. Year: 2021) Chassis No: MH3SG5680MK097172
Colour: Black Odometer: 9318 km
Engine Capacity: 155 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 110/70-13 Rear Tyre Size: 130/70 R13
Front Left Side: IRC 7 mm Rear Left Side: IRC 7 mm
Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,813.50	762.30	1,051.20	57.97
Miscellaneous Items	0.00	0.00	0.00	
Labour	280.00	220.00	60.00	21.43
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,093.50	982.30	1,111.20	53.08
Approved Total (Overridden) (S\$)		750.00		
(S\$)	2,093.50	750.00	1,343.50	64.17
+ GST 7.00/7.00% (S\$)	146.55	52.50	94.05	64.18
Nett Amount (S\$)	2,240.05	802.50	1,437.55	64.17

INSPECTION

Date of Assignment: 28/03/2022
Date Inspected: 30/03/2022 Inspected At: Teo Spray Painting (HQ)
BLK 6 DEFU LANE 10, DEFU IND PARK C #01-558
Singapore 539187
Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 26 Apr 2022)	
Parts:	N/A	YAMAHA NMAX155 155cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBT3361J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT COVER SIDE 1 RH	Cut	50.00 FL	*50.00 FL
2	1		*BODY COWLING RH	Cut	68.00 FL	*68.00 FL
3	1		*PANEL 1	Cut	45.00 FL	*45.00 FL
4	1		*PANEL 2	Not Necessary	45.00 FL	*- FL
5	1		*MOLE COVER 1	Cut	48.00 FL	*48.00 FL
6	1		*MOLE COVER 2	Cut	48.00 FL	*48.00 FL
7	1		*LOWER COVER	Cut	58.00 FL	*58.00 FL
8	2		*EMBLEM	Necessary	24.00 FL	*24.00 FL
9	1		*TAIL COVER	Cut	58.00 FL	*58.00 FL
10	1		*EMBLEM 3D	Necessary	30.00 FL	*30.00 FL
11	1		*BELT COVER	Cut	65.00 FL	*65.00 FL
12	1		*EXHAUST COVER	Cut	48.00 FL	*48.00 FL
13	1		*FOOTBOARD COVER RH	Cut	75.00 FL	*75.00 FL
14	1		*FOOTBOARD COVER LH	Cut	75.00 FL	*75.00 FL
15	1		*RADIATOR COVER	Serviceable	48.00 FL	*- FL
16	1		*SIDE STAND	Repair	35.00 FL	*- FL
17	1		*MAIN STAND	Cut / Bent	80.00 FL	*80.00 FL
18	1		*BALANCER	Cut	12.00 FL	*12.00 FL
19	1		*BRAKE LEVER LH	Cut	28.00 FL	*28.00 FL
20	1		*SIDE MIRROR LH	Cut	35.00 FL	*35.00 FL
21	1		*HANDLE BAR	Not Necessary	85.00 FL	*- FL
22	1		*FRONT FORK	Not Necessary	480.00 FL	*- FL
23	1		*STEERING CONE	Not Necessary	95.00 FL	*- FL
24	1		*UNDERBRACKET	Not Necessary	380.00 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	2,015.00	847.00
- List Item Discount on L Items 10.00/10.00% (S\$)	201.50	84.70
Total Parts (S\$)	1,813.50	762.30

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES	New	280.00	220.00
			Gross Labour Cost (\$)	280.00
				220.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >