

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9804Y*Not Notified
Penny B4 paint**8 2456.20***AAD2203-****28 MAR 2022**

Vehicle No.:

Chassis No.:

Co UEN:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

SHD9804Y

JTDKB3FU903092321

200303878K

TOYOTA

PRIUS GEN 4

25/03/2022

SJM2164K/AIG

14/05/2021

	PART
1	COVER, REAR BUMPER
1	REINFORCEMENT SUB-ASSY, REAR BUMPER
1	COVER, REAR BUMPER, LOWER
1	GUARD, REAR BUMPER, CENTER
1	RETAINER, REAR BUMPER SIDE, LH
1	RETAINER, REAR BUMPER SIDE, RH
1	LENS & BODY, REAR COMBINATION LAMP, RH
1	LENS & BODY, REAR COMBINATION LAMP, NO.2 RH.
1	PANEL SUB-ASSY, BACK DOOR
1	PLATE, LUGGAGE COMPARTMENT DOOR NAME, NO.2
1	PLATE, BACK DOOR NAME, NO.1
1	ORNAMENT SUB-ASSY, BACK DOOR
1	GARNISH SUB-ASSY, BACK DOOR, OUTSIDE
1	WEATHERSTRIP, BACK DOOR
1	COVER, FLOOR UNDER, NO.1 LH
1	COVER, FLOOR UNDER, NO.2 RH
1	COVER, REAR FLOOR CTR
1	COVER, DECK TRIM, REAR
1	PANEL SUB-ASSY, BODY LOWER BACK
1	STAY ASSY, BACK DOOR, LH
1	STAY ASSY, BACK DOOR, RH
1	HINGE ASSY, BACK DOOR, LH
1	HINGE ASSY, BACK DOOR, RH
1	COVER, FRONT BUMPER
1	BRACKET, FRONT BUMPER EXTENSION MOUNTING
1	REINFORCEMENT SUB-ASSY, FRONT BUMPER
1	ABSORBER, FRONT BUMPER ENERGY

LIST

\$	Bu	485.60	—
\$	Bu	332.70	✓
\$	Ret	22.00	—
\$	Ret/Ln	374.50	—
\$	Ln	132.60	}
\$	Ln	132.60	
\$	Ln	339.60	
\$	Ln	261.00	
\$	N	1,147.80	
\$	na	54.60	
\$	na	54.60	
\$	na	47.90	
\$	Ln	913.60	
\$	Ln	372.30	
\$	Ln	175.10	}
\$	Ln	241.90	
\$	Ln	229.90	
\$	Ln	126.70	
\$	N	651.00	
\$	Ln	242.50	
\$	Ln	242.50	
\$	N	61.00	
\$	N	61.00	
\$	Bu	521.00	✓
\$	Ln	110.50	X
\$	N	716.60	X
\$	Ln	80.20	X

Trans-cab Auto Services Pte Ltd

AAD2203-

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9804Y

1	GRILLE SUB-ASSY, RADIATOR	\$	Sn 422.50	X
1	GRILLE, RADIATOR, LOWER NO.1	\$	Sn 178.60	X
1	EMBLEM ASSY, RADIATOR GRILLE	\$	cm 105.80	✓

TOTAL \$ 8,838.20**25% \$ 2,209.55****\$ 6,628.65****Special Nett**

1SET PARKING AID	\$	Sn 700.00	X
1SET REAR BUMPER CLIP	\$	na 95.00	60sn
2 WINDSCREEN SEALANT	\$	na 150.00	} X
1 WINDSCREEN MOULDING	\$	na 200.00	
1 WINDSCREEN INNER SPONGE SEAL	\$	na 130.00	
1 REAR TAILGATE STICKER "Trans-Cab"	\$	na 80.00	
1 REAR TAILGATE STICKER "6555-3333"	\$	na 80.00	
1 REAR BUMPER PROTECTOR	\$	na 180.00	} X
1SET REAR BUMPER RETAINER CLIP	\$	na 85.00	
1 END PANEL TRIM CLIP	\$	na 65.00	
1SET BUMPER CLIP FRT	\$	na 95.00	60sn
1 FRONT NUMBER PLATE WITH MOULDING	\$	Bz 200.00	45sn
1 REAR NUMBER PLATE WITH MOULDING	\$	Sn 200.00	X
1SET FRNT BUMPER RETAINER CLIP	\$	na 85.00	X

TOTAL \$ 2,345.00**TOTAL PARTS \$ 8,973.65****LABOUR**

To Remove And Refit Rear Big and Small W/Screen Glass To Facilitate Bodywork Repair.

\$ na 300.00 X

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$ na 380.00 X

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same

\$ 2,200.00 400

Trans-cab Auto Services Pte Ltd**AAD2203-**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9804Y

To transfer of rear end panel fittings, attachment and perform water seepage test.

\$ *nn* 380.00 X

To transfer of Tailgate fittings, attachments and perform water seepage test.

\$ *nn* 180.00 X

To remove and refit electrical wiring, battery and other necessary items to facilitate bodywork repair.

\$ *nn* 480.00 X

To transfer of Fender fittings, attachments and perform water seepage test.

\$ *nn* 480.00 X

To dismantle and refit aircon assy and attachment, vacuum and charge-in-gas.

\$ *nn* 380.00 X

Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.

\$ *nn* 380.00 X

To check steering geometry and computer wheel alignment

\$ *nn* 220.00 X

To Rust-Proofing and apply undercoat Of The Affected Areas.

\$ *nn* 250.00 X

Towing Fees

\$ *nn* 150.00 X

Putty And Spray Painting Of The Affected Portion.

\$ 2,200.00 *480*

To reinstall rear bumper parking sensor.

\$ 170.00 *50*

To Check Electrical Lighting Concerned.

\$ 170.00 *20*

To transfer of luggage floor panel fittings, attachment and perform water seepage test.

\$ *nn* 380.00 X

To transfer of tire, rim and on wheel balancing.

\$ *nn* 220.00 X

Trans-cab Auto Services Pte Ltd

AAD2203-

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9804Y

To conduct and perform a comprehensive vehicle diagnostic check
and reset vehicle warning indicators.

\$ *nn* 380.00 X
TOTAL \$ **9,300.00**

Over All Total \$ **18,273.65**

(PART-BY-PART) Repair Days**25 DAYS***3 days*

Date of Submission

25/03/2022 15:22 (SGT)

Date of Accident

25/03/2022 11:50 (SGT)

Exact Location of Accident

Near AYE, Singapore

Additional Location Information

AYE TOWARDS CITY NEAR BUONA VISTA

Country/State of Loss

Singapore

Vehicle Registration Number

SHD9804Y

Is it a company vehicle?

Yes

Is company?

Yes

Name of Registered Owner

TRA

Company Reg No

200

Email Address

dair

Mobile Phone No

(Pho)

Alternative Phone No

(On)

Vehicle Part Damage

Manufacturer

Toyota

Model

Prius

Variant

SDR HATCHBACK (AUTO)

Exact purpose for which vehicle was being used at time of accident

Private hire

Are you claiming under your own insurance policy for repair to your vehicle?

No - Claiming third party

Vehicle Category

Taxi

Transmission

Auto

CC

1767

Insurance Company

AXA

Name of Insurance Company

AXA Insurance Pte Ltd

Type of Coverage

Third Party

Fleet Policy

Yes

Policy Number

VFXP2413957

Cover Note Number

NA

Driver

Name of Driver

LAU LIANG SOON

NRIC No

SXXGX887E