

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22002882/GQY3N2**Date:** 25/05/2022**REFERENCE**Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSNA00130892101

Claimant Vehicle No : FBR3437K**Insured Vehicle No :** GBF4644K

Date of Loss: 27/03/2022

Nature of Claim: TP

Claim No: SNM22D202120/C02/IRENE

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **FBR3437K**

Make & Model: YAMAHA AEROX 155A, 155cc

Engine No: G3M1E050475

Reg. Date: 14/05/2020 (Man. Year: 2020)

Chassis No: MLESG584111050498

Colour: Blue

Odometer: 38449 km

Engine Capacity: 155 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 90/80-14

Rear Tyre Size: 100/80-14

Front Left Side: Maxxis 4 mm

Rear Left Side: Maxxis 4 mm

Front Right Side: 0 mm

Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,320.00	1,497.70	3,822.30	71.85
Miscellaneous Items	0.00	0.00	0.00	
Labour	500.00	250.00	250.00	50.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	5,820.00	1,747.70	4,072.30	69.97
Approved Total (Overridden) (\$\$)		1,400.00		
(\$\$)	5,820.00	1,400.00	4,420.00	75.95
+ GST 7.00/7.00% (\$\$)	407.40	98.00	309.40	75.95
Nett Amount (\$\$)	6,227.40	1,498.00	4,729.40	75.95

INSPECTION

Date of Assignment: 10/04/2022

Date Inspected: 29/03/2022 Inspected At:

Erzat Lee Motor Trading Pte Ltd (HQ)
Synergy@KB 25 ,, Kaki Bukit Road 4 #03-37
Singapore 417800

Estimated Period of Repair: 2.0 days

Adjuster: XING GUO QIANG**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 25 May 2022)	
Parts:	N/A	YAMAHA AEROX 155A 155cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBR3437K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FORK T UNDER BRACKET	Not Necessary	400.00 F	*- FL
2	1		*FRONT TYRES SHAFT	Not Necessary	150.00 F	*- FL
3	1		*HANDLE BAR	Bent	350.00 F	*96.00 FL
4	1		*HANDLE BAR END	Cut	100.00 F	*20.00 FL
5	1		*BRAKE LEVER (R)	Cut	120.00 F	*45.00 FL
6	1		*MIRROR SET	Cut	150.00 F	*40.00 FL
7	1		*FRONT SIGNAL LIGHT (R)	Broken	200.00 F	*48.00 FL
8	1		*INNER COVER (R)	Cut	280.00 F	*108.00 FL
9	1		*FRONT FOOTREST COVER	Cut	250.00 F	*78.00 FL
10	1		*FOOTREST UNDER COVER	Cut	180.00 F	*74.00 FL
11	1		*REAR FOOTREST (R)	Cut	150.00 F	*35.00 FL
12	1		*BODY UNDER COVER	Not Necessary	280.00 F	*- FL
13	1		*EXHAUST COVER	Cut	200.00 F	*86.00 FL
14	1		*HEAD LIGHT	Cut	700.00 F	*255.00 FL
15	1		*FRONT MUD GUARD	Broken	230.00 F	*112.00 FL
16	1		*PANEL COVER	Broken	200.00 F	*122.00 FL
17	1		*FAIRING COVER	Cut	350.00 F	*118.00 FL
18	1		*REAR FAIRING COVER	Cut	280.00 F	*116.00 FL
19	1		*STEERING CONE	Necessary	200.00 FS	*80.00 FS
20	1		*FORK SET (LOCAL REPAIR)	Bent	550.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	5,320.00	1,633.00
- List Item Discount on L Items 0.00/10.00% (S\$)	0.00	135.30
Total Parts (S\$)	5,320.00	1,497.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR	New	500.00	250.00
Gross Labour Cost (\$\$)			500.00	250.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >