ASS. REO. BY:	22002 f83/ky
Kenneth	SSIGNMENT
From: Date:	Veh No: SKW 8914 Jrr Regn: 11, 15
Estimated Cost:	Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
OD VIP WS / TP RES / OD RES / EVA / INV / MY	Years 19 H
To Inspect Vehicle No:	Make: Honda Mubilo c.c 149;
at Workshop m/s Au burn	- NO. INSUREDISTANTINA
0501	
Insured:	Eng/No:
Policy No.	CNO: MR4DO4870FP000410
Claims No.	Gen. Cond: 8000 / Fair / Poor / Burnt
Sum Insured: Excess:	Steering: Inorde/ Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inorder / Jammed / Leaked / Burnt or
Make of Veh:	Modi: NII / S/RIm / STO A/Rim or
	Tyre Size: F: Falker 185/15R15
(Policy Condition)	R: Nexen —
Remark: The veh had commenced its N/S O/S	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
repair at the time of inspection.	TOYO/YOKO or
Bal, or Market Value:	<u>Front</u> <u>Rear</u>
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. 6 mm R/Bal. 6 mm
GIA / PR Seen: Consistent? : Yes or No	L/Bal. 6 mm L/Bal. 6 mm
Est. Repairs: 5-6 days Res.: Yes or No	D.O.A. 24/3/2 D.O.I. 30/3/20
Lum Sum: 20 % 3 Val.: Yes or No	Survey held at
CA / REV / REP. / 24 HRS	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
· Vehicle: IN / OUT	
	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction	The sould consider
Tailpole journel, Sot BI	
	The same of the sa
ata/Time, File Pass to? Prell. Report D	Days Of Repair:
	Annual III
sta/Time, File Return to?	MANAGEMENT AND
Add Fee:	Site Inco. /\$
Add Fee:	: Site Insp (\$)_s-Rs_si
<u></u>	: Interview (\$) F.E.S
port Format :	Tech Invs (\$). Others
np Sum / I.B.I: (S	Weakend (\$
	And the state of t
	107AL

Not Nothair USay & Presung After Pains Eday

AUBURN AUTO PTE LTD

176 Sin Ming Drive #04-18 Sin Ming Autocare, Singapore 575721

Tel: +65 9773 6360

1

Email: mak.auburnauto@gmail.com

Vehicle No: SKW8914J Model: Honda Mobilo

QTY	Description		Repa	irer's Estimate
	Spare Parts -	List Items		
1	Rear Tailgate		\$	3,200.00
2	Rear Taillamp		\$	c par 2,200.00
2	Rear Tailgate Lar	np	\$	cm 920.00 _
1	Rear Tailgate Me		\$	800.00 7
1	Rear Tailgate Loc	ck .	\$	7m 480.00 -
1	Inner lock		\$	№ 240.00 ⊀
1	Outer lock		\$	5 180.00 ⊀
1	Upper Lock		\$	5 325.00 ⊀
1	Lower Lock		\$	5 422.00 X
1	Rear Windscreen	Seal	\$	Ma 205.00 30sa
1	Rear Bumper		\$	2 ,800.00 —
1 .	Rear Bumper Side	e Retainers	\$	Diy 428.00 -
1	Bumper Sensor		\$	320.00 ×
1	Rear Bumper Ref	lectors	\$	720.00 7
1	Rear Bumper Top	Step Garnish	\$	320.00 7
1	Rear End Panel	1	\$	2,620.00 7
1	Rear End Panel In	ner Garnish	\$	580.00 7
1	Rear Boot Garnish	1	\$	CM 380.00 -
1	Hydraulic Hinge		\$	200.00
2	Rubber Moulding		\$	120.00 7
1	Number Plate		\$	ner 120.00 4552
1	Rear Exhaust		\$	2,800.00 7
1	Rear Reverse Cam	era	\$	= 5
1	Rear Tailgate "Hor		\$	320.00 7
- I	Rear Tailgate "Mol			Me 160.00 —
			\$	100.00
	Private Hire Sticke	r & inspection	\$	Ma 98.00 300m
•	Rear Windscreen	ants hence notify	uto Consult	1,300.00
		:pr2019		
		aver seray sainting	urvey before/	en of •

To resurvey before/are: Aray painting
To display opining deprile; during resurvey
Parks prices are subject to confirmation **22,438.00**

. Third party survey is on a "Without Prejudice" basis . No alegal medification(s) is allowed

. Supplementary item(s) must be resurveyed and S for ages place to final approval from Insurance Company

indiged by Repairer

\$

1 1 1	Special Nett Items Rear Windscreen Sealant Back bumper clip Rear Reverse Sensor (1 set)	\$ \$ \$ \$	MT S\$ Ner Ner Ner Rupeger	120.00 150.00 620.00 890.00	405m 605m X
S/N. 1	Labour Charges Refit rear windscreen	\$		300.00	1200
2	Remove and refit rear tailgate	\$		300.00	12d bel
3	Remove and refit rear bumper	\$		300.00	7
4	Remove and Refit Rear Panel	\$		800.00	} 6001
5	Remove, refit and replaced damage lamps and check up rear electrical wiring	\$		150.00	20
6	Remove and refit inner garnishes trim to assist repair	\$		200.00	Je1
7	Remove and refit rear reverse sensor	\$		240.00	501
8	To apply undercoating on replaced panel	\$		120.00	601
9	To Respray Painting.	\$		1,400.00	Soci
		\$		3,810.00	-
,	LKK Auto Consultants hence notify the Repairer of the following:	\$	2'	7,138.00	-
	To resurvey before/after spray painting				_

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Dale.

SF0F223S0007 / FALCON-AIR AUTO SERVICES PTE LTD [575721] ENTRY DATE & TIME: 28/03/2022 16:43 (SGT) SUBMITTED BY: Florence Loh VERSION: 1 (28/03/2022 16:43 (SGT))

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.

2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.

4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 28/03/2022 16:43 (SGT) **Date of Accident** 24/03/2022 13:30 (SGT) **Exact Location of Accident** Pasir Ris Drive 3, Singapore Additional Location Information Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SKW8914J

INSURED/POLICYHOLDER

Is company? Name Of Registered Owner ALPHA MOTORS PTE. LTD. Company Reg No 2XXXXX050H Email Address den.goldencharter@gmail.com Mobile Phone No (Phone) +65-97736360 Alternative Phone No +65-97736360

VEHICLE PARTICULARS

Manufacturer Model	Honda
Variant	Mobilio
Exact purpose for which vehicle was being used at time of accident	-
Are you claiming under your own insurance policy for repair to your vehicle?	No. Claiming thind
venicle Category	No - Claiming third party Private hire
Transmission	Auto
OC	1497

INSURANCE COMPANY

Name of Insurance Company	NTUC Income Insurance Co-operative Ltd
Type of Coverage	ThirdParty
Fleet Policy	Yes
Policy Number	5121408521-01
Cover Note Number	-

DRIVER

MUSHRIN BIN MARZUKI Name of Driver NRIC No SXXXX078C

Vehicle A- SEW8914J Vehicle B-YN3884M SKETCH PLAN Praffic light Pasinis Prive 3 Refer to police report. DECLARATION SIN I/We declare the foregoing particulars are the Reporting Centre Personnel's Signature **Oriver's Signature**

(If driver is not the policyholder)

Date & Time:

Policyholder's Signatur

Date & Time:

Name:

NRIC/FIN No.:





2 of 3

Report No. T/20220328/7022

Police Station Of Origin: Traffic Police 10 Ubi Avenue 3 SINGAPORE 408865 Tel No: 65470000

CONTINUATION OF REPORT

Driver	AAUCHDINI DIALAAA	27111/1		ID No.	S7237078C
Name	MUSHRIN BIN MARZUKI		ID NO.	3/23/0/60	
Related Vehicle	SKW8914J (Car)		Contact N	o. 91438553	
Hospital/Clinic	SINGHEALTH POLYCLINICS - PASIR RIS		Class of Driving Licence & Expiry	Class: NIL Date of Expiry: NIL	
Date	NIL		Date	NIL	La rational de la constant de la con
No. of Days granted Medical Leave 03		Degree of	Slig	ght	

Brief Details.

On 24/03/2022 around 1330Hrs, I was driving my rental car bearing SKW8914J along pasir ris drive 3 sport club towards pasir ris street 52 with my cousin and my daughter. I was stationary while waiting for the traffic light as the light was red. Out of a sudden, I heard a loud bang and felt huge impact on the rear of my car. The lorry bearing YN5884M collided on the rear of my vehicle. Both vehicle sustained damages. I was in shock but I came down to exchange details with the driver of the lorry. There were passerbys who witness what had happened and said that he was eating while driving. The driver of the lorry admitted that it was his fault so he kept apologizing and called his father to come down to the accident scene. He then asked to private settle and said will contact me later so we left after that. After 1 day passed he did not contact me, I also tried to call him but he kept giving excuses and became uncontactable after that hence I am reporting the accident now. My daughter and I also fell unwell and went to see a doctor and was given MC.