



TRANS EUROKARS PTE LTD
27A TANJONG PENJURU, SINGAPORE 609042



ESTIMATE COST OF REPAIRS

HL ASSURANCE PTE. LTD 11 KEPPEL ROAD #11-01 ABI Plaza Singapore 089057 ATTN. : MOTOR CLAIMS FAX :		NAME : ADDRESS : TEL :		WIP : 20939 EXCESS : DATE: 29-Mar-22				
VEH NO :	SMY6188S	DATE IN :		CONTACT PERSON :	RONALD			
CHASSIS NO :	JM6DJ2HAA01400110	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIM			
MODEL :	MAZDA 2	DATE REG.:	15-Jan-21	POLICY NO. :				
NATURE OF WORKS								
<u>NO</u>	<u>DESCRIPTION</u>	<u>QTY</u>	<u>UNIT PRICE</u>	<u>1st</u>	<u>Supp</u>	<u>PARTS NO</u>	<u>REVISED</u>	<u>PRICES</u>
1	REAR BUMPER	1	893.40			MD43N-50-221CBB		893.40
2	BRACKET CENTER REAR BUMPER	1	5.40			MDFR5-50-251		5.40
3	STAY REAR BUMPER	2	23.80			MD43N-50-271		47.60
4	CHORME RH REAR BUMPER	1	27.50			MD43N-50-360A		27.50
5	CHORME LH REAR BUMPER	1	27.50			MD43N-50-370A		27.50
6	RETAINER LH REAR	1	27.20			MD09H-50-2J1A		27.20
7	RETAINER RH ERAR	1	27.20			MD09H-50-2H1A		27.20
8	BRACKET LOWER REAR BUMPER	1	26.00			MD43N-50-251A		26.00
9	FASTENER	7	3.00			MB45A-56-146A		21.00
10	CAP REAR BUMPER	1	11.00			MD43N-50-705A		11.00
11	REAR END PANEL	1	477.10			MDJYS-70-75Z		477.10
12	TRIM REAR END PANEL	1	77.00			MD09W-68-89XA02		77.00
13	TAILGATE	1	956.70			MD0Y2-62-02X		956.70
14	TRIM TAILGATE LOWER	1	93.50			MD09W-68-960		93.50
15	FASTENER	9	3.00			MGJ21-68-885B02		27.00
16	CLIP,TRIM	2	3.00			MGJ12-68-865		6.00
17	RECESS TAILGATE	1	15.00			MD651-68-966A02		15.00
18	COVER,HOLE	2	2.50			MD24H-62-866		5.00
19	VALVE,ONEWAY	2	12.00			MGHP9-58-867		24.00
20	SWITCH,OPEN	1	89.70			MD09H-62-4B0C		89.70
21	LOCK TAILGATE	1	212.30			MDM0P-62-310		212.30
22	FASTENER	2	8.20			MC513-50-896		16.40
23	SPACER	4	12.80			MGJ6A-50-897		51.20
24	CLIP,GARNISH	4	5.20			MD09W-50-M38A		20.80
25	WIPER MOTOR REAR	1	333.00			MD09L-67-450A		333.00
26	GASKET RH LAMP TAILGATE	1	41.80			MD43N-51-3H8		41.80

27	GASKET LH LAMP TAILGATE	1	41.80			MD43N-51-3J8		41.80
28	BRACKET RH TAILGATE	1	23.50			MDA6A-51-3HXA		23.50
29	BRACKET LH TAILGATE	1	23.50			MDA6A-51-3JXA		23.50
30	ORNAMENT MAZDA 2	1	55.60			MD43T-51-720		55.60
31	ORNAMENT SKYACTIV	1	47.30			MDHL5-51-771		47.30
32	MASCOT,REAR	1	61.20			MD09W-51-730		61.20

SUPPLEMENTARY										
NO		DESCRIPTION		QTY	UNIIT PRICE	1st	Supp	PARTS NO	REVISED	PRICES
1										
								TOTAL PARTS		3,813.20
								TOTAL PARTS COST		3,813.20
Labour Description										
									REVISED	PRICES
1		TO REPLACE REAR BUMPER , REAR END PANEL, TAILGATE AND REPAIR ALL AREAS AFFECTED BY THE ACCIDENTS								3,960.00
2		TO RESPRAY REAR BUMPER , REAR END PANEL , TAILGATE AND ALL AREAS AFFECTED BY THE ACCIDENTS.								2,520.00
3	MZ-BR-SEALER	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING							NETT	180.00
4	MZ-BR-GLASS1	TO REMOVE & REFIT THE WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST.							NETT	560.00
5	MZ-BR-GLASS2	TO SUPPLY SEALER ON THE WINDSCREEN GLASS.							NETT	120.00
6	MZ-BR-TAILME	TO TRANSFER TAILGATE MECHANISM.								660.00
7	MZ-BR-REVSEN	TO TRANSFER REVERSE SENSORS.								660.00
8	MZ-BR-CAMERA	TO TRANSFER REVERSE CAMERA.								660.00
9	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.								250.00
10	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.								300.00
11	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.(INCLUDING NEW PARTS AND CAOUTCHOU)								150.00

12	MZ-BR-SUNDRI	SUNDRIES.		50.00
SUPPLEMENTARY LABOUR DESCRIPTION				
1		#N/A		
REMARKS: THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400 WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.			TOTAL LABOUR	- 10,070.00
			TOTAL PARTS	- 3,813.20
			TOTAL	- 13,883.20
			LESS EXCESS	- -
			TOTAL AFTER EXCESS	- -
			GST 7%	- -
			GRAND TOTAL	- -

TRANS EUROKARS PTE LTD

 Authorised Signature