

SPRAYSMITHS PTE LTD

1 Kaki Bukit Ave 6 #01-22, Kaki Bukit Autobay, Singapore 417883

Tel: 69090886, Fax: 69090885

not Allowed
due
reasons
29/3/22
2/5 \$7500/
the photo After repair
9 days.

TO :		DATE : 29-Mar-22	
OWNER'S PARTICULAR		VEHICLE DETAILS	
NAME :		VEHICLE NO :	SJD1831D
ADDRESS :	NIL	MODEL :	Honda Civic 1.8
TEL. NO. :	NIL	CHASSIS NO :	
ACCIDENT DETAILS		DATE :	
		TIME :	
THIRD PARTY REQUESTOR / CONTACT :			

QUOTATION SUMMARY

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	Front bumper <i>70cm</i>	1	<i>638</i>	\$ 783.70
2	Front bumper beam <i>NS</i>	1		\$ 210.50
3	Front bumper reinforcement <i>NS</i>	1	<i>302.70</i>	\$ 365.40
4	Front bumper number plate base garnish <i>1P</i>	1		\$ 222.40
5	Front bumper side bracket <i>11</i>	2		\$ 76.00
6	Front bumper side retainer <i>best</i>	2	<i>25 x 2 = 50</i>	\$ 124.40
7	Front bumper fog lamp <i>11</i>	2		\$ 480.00
8	Head lamp (HID) <i>holder CR</i>	2		\$ 1,763.60
9	Head lamp lower bracket <i>R</i>	2		\$ 180.60
10	Front radiator grille <i>CR</i>	1	<i>168.20</i>	\$ 285.00
11	Front grille chrome <i>SCR</i>	1	<i>165.30</i>	\$ 225.50
12	Front grille H logo <i>SCR</i>	1	<i>38.22</i>	\$ 43.80
13	Front support panel assy <i>R</i>	1		\$ 526.00
14	Front bonnet <i>best</i>	1	<i>606.20</i>	\$ 875.80
15	Front bonnet lock <i>SCR</i>	1		\$ 81.80
16	Front fender <i>11</i>	2		Repair
17	Air con condenser <i>11</i>	1		\$ 701.20
18	Front radiator <i>11</i>	1		\$ 1,167.10
19	Front radiator fan motor and cowling <i>11</i>	1		\$ 420.20
20	Rear boot lid <i>body</i>	1	<i>610.20</i>	\$ 810.70
21	Rear boot lid insulator <i>11</i>	1		\$ 161.60
23	Rear boot lid H emblem <i>11</i>	1		\$ 39.20
24	Rear boot lid reflector <i>N/S CR</i>	1	<i>148.50</i>	\$ 472.80
25	Rear boot lid lock <i>best</i>	1	<i>109.50</i>	\$ 234.50
26	Rear boot lid hinge <i>11</i>	2		\$ 220.00
27	Rear boot lid weather-strip <i>1W1</i>	1		\$ 105.60
28	Tail lamp <i>CR</i>	1	<i>302 x 2 = 604</i>	\$ 760.00
29	Rear end panel <i>body</i>	1	<i>336</i>	\$ 469.50
30	Rear end panel top garnish <i>1W1</i>	1		\$ 89.60
31	Rear bumper <i>11</i>	1		\$ 683.70
32	Rear bumper side retainer <i>N/S CR</i>	2	<i>0.5 x 11 = 5.5</i>	\$ 56.00
33	Rear bumper side bracket <i>best</i>	2	<i>12 x 2 = 24</i>	\$ 58.00

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	Rear number plate 11	1		\$ 40.00
2	Rear boot lid insulator clips 11	10		\$ 50.00
3	Rear bumper clips 7.22	10	1 set	\$ 50.00
4	Rear fender inner trim board clips 11	16		\$ 60.00
5	Front bumper clips 11	10		\$ 50.00
6	Front number plate CSQ	1		\$ 40.00
7	End panel sealant 11	1		\$ 120.00
8	Rear bumper reverse sensor short	2		\$ 250.00
9	Rear exhaust chrome tip SVC	1		\$ 250.00
10	Rear bumper lower body kit 7.15	1		\$ 800.00

TOTAL**\$1,710.00****CLAIM DETAILS: LABOUR**

S/N	JOB DESCRIPTION	PRICE	APPROVED
1	To provide labour, workmanship to change damaged bodyparts, repair, align body structure & damaged and where consistent to the accident.	\$ 1,800.00	1100
2	To respray, painting on the change bodyparts, repair portion and where consistent to the accident.	\$ 1,800.00	1600
3	To remove, reinstall electrical wiring and check lighting.	\$ 60.00	30
4	To remove, replace and refit rear exhaust pipe.	\$ 120.00	11 X
5	To remove, refit and replace air con condensor. Top up gas.	\$ 150.00	11 X
6	To remove, replace and refit rear boot lid and lock mechanism.	\$ 120.00	60
7	To remove, refix and replace interior trims, seat assy, floorboard carpet and etc to faciliate the repair.	\$ 180.00	80
8	To tuff kote and underseal materials	\$ 120.00	90
9	To remove and replace rear reverse sensor	\$ 80.00	50
TOTAL		\$ 4,430.00	

ESTIMATE REPORT

TOTAL PARTS COST : \$13,330.24
 TOTAL LABOUR COST : \$ 4,430.00
 TOTAL REPAIR COST : **\$17,760.24**

APPROVED DETAILS

EXCESS :
 NO. OF WORKING DAYS :
 RE-SURVEY :
 PART BY PART OR LUMP SUM :
 DATE & TIME OF SURVEY :
 SURVEYED BY :
 CONTACT NUMBER :
 FAX NUMBER :

LKK Auto Consultants hence notify
 the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-6683.7
 202
 P-5346.96
 S.N-1030
 L-3010
 9386.96
 202
 7509.