

TwinCar AUTOMOTIVE PTE LTD

K... AutoHub
2 K... Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

TP Budget Direct
Veron

TAX INVOICE

SJ AUTO PTE LTD
170 UPPER BUKIT TIMAH ROAD #03-50
SINGAPORE 588179

Repair Code : CLM15481

Date in : 28/03/2022

Vehicle Num. : SLL6558M

Model : HONDA SHUTTLE 1.5G CVT

Chassis/Eng# : GK81101044/L15B5001247

Contact : 85255530, 86175875 ✓

Auto General

Parts and Labour Assessment

Description of part	Qty	Unit Price	Amount
FRONT BUMPER <i>Dehd</i>	1	1050.00	<i>858</i> 1,050.00
FRONT BUMPER LH COVER <i>3 new</i>	1	33.20	+ 33.20
FRONT BUMPER LH GRILLE COVER	1	25.00	+ 25.00
FRONT BUMPER SIDE RETAINER L/R <i>LH Dmg</i>	2	15.70	<i>15.70</i> 31.40
FRONT GRILLE <i>3 new</i>	1	395.00	+ 395.00
FRONT GRILLE CHROME MOULDING	1	302.50	+ 302.50
FRONT LH ABS SENSOR	1	198.90	+ 198.90
FRONT LH FENDER <i>Repair</i>	1	435.00	+ 435.00
FRONT LH FENDER INNER SHIELD <i>the new</i>	1	110.50	+ 110.50
FRONT LH HEADLAMP <i>cracked</i>	1	2250.00	✓ 2,250.00
FRONT LH HEADLAMP LOWER BRACKET <i>the new</i>	1	38.00	+ 38.00
FRONT LH KNUCKLE ARM <i>Dmg</i>	1	395.00	✓ 395.00
FRONT LH KNUCKLE ARM BEARING <i>Dmg</i>	1	168.00	✓ 168.00
FRONT LH LINKAGE <i>new</i>	1	50.60	+ 50.60
FRONT LH LOWER ARM <i>Best</i>	1	355.00	✓ 355.00
FRONT LH SHOCK ABSORBER <i>Best</i>	1	480.00	<i>391</i> ✓ 480.00
FRONT LH SHOCK ABSORBER TOP MOUNTING <i>new</i>	1	40.00	+ 40.00
FRONT LH STEERING TIE ROD <i>Best</i>	1	95.60	✓ 95.60

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200714616M
 GST Registration No. : 200714616M

SJ AUTO PTE LTD
 170 UPPER BUKIT TIMAH ROAD #03-50
 SINGAPORE 588179

Contact : 85255530, 86175875

TAX INVOICE

Repair Code : CLM15481

Date in : 28/03/2022

Vehicle Num. : SLL6558M

Model : HONDA SHUTTLE 1.5G CVT

Chassis/Eng# : GK81101044/L15B5001247

FRONT LH STEERING TIE ROD END <i>Mem</i>	1	71.80	<i>X</i>	71.80
FRONT LH WHEEL HUB <i>2nd</i>	1	138.40	<i>✓</i>	138.40
LH SIDE MIRROR	1	527.70	<i>X</i>	527.70
LH SIDE MIRROR COVER <i>HP</i>	1	47.30	<i>X</i>	47.30
LH SIDE MIRROR LOWER COVER <i>Nec</i>	1	35.80	<i>X</i>	35.80
Subtotal before discount				7,274.70
Percentage discount 20%				1,454.94
Sub-total 1				5,819.76
FRONT BUMPER CLIPS - SET <i>Mem</i>	1	50.00	<i>30</i>	50.00
FRONT GRILLE CLIPS - SET <i>Mem</i>	1	50.00	<i>X</i>	50.00
FRONT LH FENDER INNER SHIELD CLIPS - SET <i>Mem Mem</i>	1	50.00	<i>X</i>	50.00
FRONT LH SPORT RIM <i>Best</i>	1	800.00	<i>450</i>	800.00
FRONT LH TYRE <i>Deband</i>	1	400.00	<i>180</i>	400.00
Subtotal before discount				1,350.00
Percentage discount 0%				0.00
Sub-total 2				1,350.00
Parts-total				7,169.76

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

SJ AUTO PTE LTD
170 UPPER BUKIT TIMAH ROAD #03-50
SINGAPORE 588179

Contact : 85255530, 86175875

TAX INVOICE

Repair Code : CLM15481

Date in : 28/03/2022

Vehicle Num. : SLL6558M

Model : HONDA SHUTTLE 1.5G CVT

Chassis/Eng# : GK81101044/L15B5001247

LABOUR

To remove, reinstall electrical wiring harness, check lighting. (to FR)

To remove, change front suspension parts, absorber, lower arm, knuckle arm, wheel bearing, bearing hub, drive shaft, anti-roll bar, top-arm and steering rack and pinion.

To road test driving, check and resetting wheel alignments system.

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

30 60.00

200 250.00

80 100.00

400 700.00

400 700.00

30 50.00

1140

Labour Total

1,860.00

Parts & Labour Total

9,029.76

*** This is a computer-generated document which requires no signature.***

page 3

total: 5613.36

A/S: 4.5K

06 Days

4.5K

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: