

CONNECT 3

566 Woodlands Road (Mandai Estate) Singapore 728697
Tel: (65) 9850-9666 Email: Connect3winnie@gmail.com

Reg: 53360061L

GST: 53360061L

Steve (LKK)

30/3/22, 3:22pm

WIL PL

18 Lys

LIS

47 AL 17

QT22/PC1165X/TPC

China Taiping Insurance (Singapore) Pte Ltd
3 Anson Rd #15-02
Springleaf Tower
Singapore 079909

QUOTATION

Dear Sir,

Cost of Repair to Vehicle PC1165X

With reference to the above-mentioned, we are pleased to quote as follows:-

No.	DESCRIPTION	QTY	U/PRICE (S\$)	AMOUNT (S\$)
1.	Rear end panel (upper) / 00	1	2,800.00	2,800.00
2.	Rear end panel grille (lower) / 00	1	3,200.00	3,200.00
3.	Rear LH taillamp / BR	1	1,850.00	1,850.00
4.	Rear LH taillamp panel inner structure / 00	1	2,000.00	2,000.00
5.	Rear tailgate (lower) / 00	1	4,200.00	4,200.00
6.	Rear tailgate inner structure / 00	1	1,800.00	1,800.00
7.	Rear tailgate grille / 00	1	630.00	630.00
8.	Rear tailgate lock X 00	1	580.00	580.00
9.	Rear tailgate stopper X 00	2	235.00	470.00
10.	Rear tailgate hinges / BT	4	250 285.00	1,140.00
11.	Rear tailgate sensor X 00	2	350.00	700.00
12.	Rear tailgate gas spring / BT	2	115.00	230.00
13.	Rear tailgate brackets / BT	2	300 385.00	770.00
14.	Rear LH taillamp panel fibre / BR	1	2,100.00	2,100.00
15.	Rear LH taillamp panel inner structure / 00	1	970.00	970.00

1500/

2800/

/

1900/

3800/

1600/

/

1000/

/

115/

600/



/

/

16.	Rear LH side panel / 00	1	4,800.00	4,800.00	4500/
17.	Rear LH last piece compartment cover / 00	1	1,750.00	1,750.00	1500/
18.	Rear LH last piece compartment cover grille / 00	1	470.00	470.00	/
19.	Rear LH last pc compartment gas spring / BT	2	185.00	370.00	/
20.	Rear LH last pc compartment inner base structure / 00	1	850.00	850.00	/
21.	Rear pulley X nn	1	1,860.00	1,860.00	
22.	Fan belt 2 / Tn	1	890.00	890.00	300/
23.	Radiator assy ? / BT	1	4,650.00	4,650.00	4500/
24.	Radiator assy base and bracket ? X nn	1	1,020.00	1,020.00	
25.	Radiator fan cowling ? / BT	1	740.00	740.00	/
26.	Radiator fan blades 2 X nn	1	240.00	340.00	
27.	Sealant / RL	15	40.00	600.00	/ nett
28.	60KM/H sticker / RL	1	15.00	15.00	/ nett
29.	Reverse sensor / DR	1	380.00	380.00	200/ nett
30.	Labour to remove & refit rear windscreen to assist repair	1	400 500.00	500.00	
31.	Labour to remove & refit LH side glasses to assist repair	1	1800 2,400.00	2,400.00	
32.	Labour to remove & refit LH side seats, trims, upholstery etc to assist repair	1	600 900.00	900.00	
33.	Labour to remove rear seats, trims, upholstery etc to assist repair	1	500 600.00	600.00	
34.	Spray foam	1	300 500.00	500.00	
35.	Apply anti rust	1	150 200.00	200.00	
36.	Check wiring	1	50 100.00	100.00	
37.	Labour charges	1	3600 4,200.00	4,200.00	
38.	Spray painting + (design)	1	3000 3,600.00	3,600.00	
	SUB-TOTAL			SS55,175.00	

• Price exclude 7%gst P-33,095 N-815 L-10,400 Supp-5834-70
 -10%
 29,785.50
 = 46,835.20
 L/S-37,468-16
 = 37,450

Yours faithfully,



Winnie Chai
HP: 9850-9666

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

CONNECT 3

566 Woodlands Road (Mandai Estate) Singapore 728697

Tel: (65) 9850-9666 Email: Connect3winnie@gmail.com

Roc: 53360061L

GST: 53360061L

Supp.

QT22/PC1165X/TPC

China Taiping Insurance (Singapore) Pte Ltd
3 Anson Rd #15-02
Springleaf Tower
Singapore 079909

QUOTATION

Dear Sir,

Cost of Repair to Vehicle PC1165X (Supp Items)

With reference to the above-mentioned, we are pleased to quote as follows:-


No.	DESCRIPTION	QTY	U/PRICE (S\$)	AMOUNT (S\$)
1.	<i>Inter cooler</i> Radiator Assy <i>BT</i>	1	7,056.00	7,056.00 <i>3500/</i>
2.	Cap Radiator <i>X NN</i>	1	53.00	53.00
3.	Pipe; hose to hose, Radiator outlet <i>X Rink</i>	2	345.00	690.00
4.	Hose; water rad to pipe <i>X Rink</i>	3	47.00	141.00
5.	Hose ; Rad to surge tank <i>X Rink</i>	3	45.00	135.00
6.	Radiator bracket <i>BT</i>	<i>81</i>	142.00	852.00 <i>✓</i>
7.	End asm; rad tie rod LH <i>X NN</i>	3	32.00	96.00
8.	End asm; rad tie rod RH <i>X NN</i>	3	32.00	96.00
9.	Radiator space tank <i>X NN</i>	1	42.00	42.00
10.	Coupling Fan Clutch <i>BT</i>	1	1,323.00	1,323.00 <i>✓</i>
11.	Fan Cooling (<i>Black</i>) <i>CVT</i>	1	573.00	573.00 <i>300/</i>
12.	Cooling Fan belt <i>TH</i>	2	74.00	148.00 <i>✓</i>
13.	Link Asm; Adj cooling fan drive pully <i>Jammed</i>	1	176.00	176.00 <i>✓</i>
14.	Bracket; Adj link rod, Fan belt <i>BT</i>	1	184.00	184.00 <i>✓</i>

6483
-10%
5834.70

		SUB-TOTAL	S\$11,565.00
--	--	------------------	---------------------

- Price exclude 7%gst

Yours faithfully,



Winnie Chai
HP: 9850-9666

