

Repair Estimate

Thiam Heng Huat Pte Ltd

176 Sin Ming Drive #05-14 Sin Ming Autocare Singapore 575721

Mobile: 82636295 Email: thiamhenghuat@gmail.com

NOT Authorized
11 May @ 1800h
Penny After Paint

Make/Model: NISSAN P/UP

Engine/Chassis No.: JN1CHGD22Z0071643

Date of accident:

Damaged area: Rear

Date: 04/04/2022

Claim Type: TP

VRN: GBG6260R



List items				
S/N	Parts description	QTY	UNIT PRICE	AMOUNT
1	Tailgate	1	\$ 1,573.00	\$ 1,573.00
2	Tailgate lock	1	\$ 185.00	\$ 185.00
3	Tailgate lock catch	1	\$ 69.00	\$ 69.00
4	Tailgate "NISSAN" logo	1	\$ 62.00	\$ 62.00
5	Tailgate outer handle	1	\$ 165.00	\$ 165.00
6	Taillamp	2	\$ 651.00	\$ 1,302.00
7	Taillamp panel	2	\$ 162.00	\$ 324.00
8	Taillamp lower garnish	2	\$ 85.00	\$ 170.00
9	Rear bumper 900	1	\$ 1,191.00	\$ 1,191.00
10	Rear bumper reinforcement	1	\$ 432.00	\$ 432.00
11	Rear bumper lower bracket	4	\$ 46.00	\$ 184.00
12	Rear bumper step moulding center 275	1	\$ 289.00	\$ 289.00
13	Rear bumper step moulding main 425	1	\$ 445.00	\$ 445.00
14	Rear bumper step moulding base	1	\$ 271.00	\$ 271.00
15	Rear licence plate lamp 056-40	2	\$ 128.00	\$ 256.00
Subtotal				\$ 6,918.00
List discount				10.00%
Total				\$ 6,226.20

Special nett items				
No.	Parts description	QTY	UNIT PRICE	AMOUNT
1	Tailgate "70km/h" sticker	1	\$ 25.00	\$ 25.00
2	Tailgate company sticker	1	\$ 100.00	\$ 100.00
3	Tailgate aluminium board	1	\$ 500.00	\$ 500.00
4	Rear bumper clips	12	\$ 5.50	\$ 66.00
5	Sundries	1	\$ 50.00	\$ 50.00
Total				\$ 741.00

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

155n
305n
X
X
X

Repair Estimate

Labour

No.	Description	Work unit	Amount
1	To dismantle / renew the accident damaged portion. To panel beat, reshape, straighten, orientate and align repair / replacement parts.	6	\$ 1,200.00
2	To disconnect rear wire harness of electrical components to facilitate repairs, reconnect and check functions including taillamp lightings.	0.25	\$ 50.00
3	To remove, refit tailgate components to replace tailgate, check and re-adjust close gap, alignment.	0.5	\$ <i>nn</i> 100.00
4	Supply spray paint material and necessary items to respray affected area / panel.	5	\$ 1,000.00
5	To rust proof all affected portions after repair.	0.5	\$ <i>nn</i> 100.00
Total labour			\$ 2,450.00

400/

15/

X

350

X

Estimate Grand Total	\$ 9,417.20
----------------------	-------------