

OPTIMA WERKZ SINGAPORE

OPTIMA WERKZ PTE LTD
Co. Reg. No. 201212455W
www.ow.sg

/OptimaWerkz

/OptimaWerkz

Date: 29/03/2022

Vehicle No: SLW3239X

Model: PEUGEOT 3008 ACTIVE PURETECH 1.2

Chassis: VF3MRHNYWHS325029-2017

Reg. Year: 2018

Third Party Insurer: CHINA TAIPING

Third Party Veh No: SJS1375T

Date of Accident: 10/02/2022

Estimator: TING AN

Surveyor:

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	FRONT DOOR LH <i>1850</i>	1		<i>Rs</i> \$2,258.48
2	FRONT DOOR LOWER GARNISH COVER LH	1		<i>Rs</i> \$333.25
3	FRONT DOOR WEATHERSTRIP LH	1		<i>Rs</i> \$151.77
4	FRONT DOOR OUTER MOULDING LH	1		<i>Rs</i> \$205.20
5	REAR DOOR LH <i>1850</i>	1		<i>Rs</i> \$2,258.48
6	REAR DOOR LOWER GARNISH COVER LH	1		<i>Not</i> \$333.25
7	REAR DOOR WEATHERSTRIP LH	1		<i>Rs</i> \$151.77
8	REAR DOOR OUTER MOULDING LH	1		<i>Rs</i> \$205.20
9	REAR DOOR UPPER HINGE LH	1		<i>Rs</i> \$126.50
10	REAR DOOR LOWER HINGE LH	1		<i>Rs</i> \$126.50
11	REAR DOOR CHECKER LH	1		<i>Rs</i> \$138.60
12	REAR DOOR WINDOW MOTOR WITH REGULATOR LH	1		<i>Rs</i> \$689.60
13	REAR DOOR INNER TRIM BOARD LH <i>1580</i>	1		<i>Rs</i> \$2,164.78
14	ROCKER PANEL LH	1		<i>Rs</i> \$2,050.90
15	B-PILLAR LH	1		REPAIR
SUB TOTAL				\$11,194.28
LESS 10%				-\$1,119.43
PARTS TOTAL				\$10,074.85

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	FRONT DOOR INNER TRIM BOARD CLIPS LH	1		<i>Rs</i> \$50.00
2	REAR DOOR INNER TRIM BOARD CLIPS RH	1		<i>Rs</i> \$50.00
3	FRONT DOOR LOWER GARNISH COVER CLIPS LH	1		<i>Rs</i> \$40.00
4	REAR DOOR LOWER GARNISH COVER CLIPS LH	1		<i>Rs</i> \$40.00
S/N TOTAL				\$180.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6481 1011 | Fax: (+65) 6481 1013

Date:

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-16 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



OPTIMA WERKZ™ SINGAPORE

OPTIMA WERKZ PTE LTD
Co. Reg. No. 201212455W
www.ow.sg

f /OptimaWerkz

● /OptimaWerkz

Date: 29/03/2022
Vehicle No: SLW3239X
Model: PEUGEOT 3008 ACTIVE PURETECH 1.2
Chassis: VF3MRHNYWHS325029-2017
Reg. Year: 2018

Third Party Insurer: CHINA TAIPING
Third Party Veh No: SJS1375T
Date of Accident: 10/02/2022
Estimator: TING AN
Surveyor:

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST ACCIDENT AREAS & ETC.

500
\$1,000.00

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT DOOR LH, REAR DOOR LH, ROCKER PANEL LH, B-PILLAR LH & ETC.

600
\$1,000.00

LABOUR CHARGES TO REMOVE & REINSTALLED FRONT & REAR DOOR INNER MECHANISM. BACK TO ORIGINAL OPERATIONS.

1200
\$250.00

TO CHECK WIRING & CENTRAL LOCKING SYSTEM.

200
\$120.00

TO TUFF KOTE & UNDERSEAL MATERIALS.

600
\$150.00

LABOUR TOTAL \$2,520.00

TING AN

TOTAL

\$12,774.85

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9010 | Fax: (+65) 6481 1093

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011

