

Your Ref : 800SWAISCL20220073SL

Date: 29th Aug 2022

Our Ref : CS4/AIS22002915/Nqy3e2

M/s Allianz Insurance Singapore Pte Ltd

79 Robinson Road #09-01

Singapore 068897

(The Motor Claims Department)

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE YN 5916E
ACCIDENT ON 19/03/2022**

Instruction was received to inspect the vehicle Reg. No. YN 5916E. The inspection was conducted on 29/03/2022 at the premises of M/s Klenco (S) Pte Ltd, 18, Gul Crescent, Singapore 629527.

The following vehicle information was recorded:

Registration Number	: YN 5916E
Make/Model	: Dulevo 5000 Veloce EU5 A
Year of Registration	: 2014
Body Colour	: White / Grey
Chassis Number	: ZA9S5020E5AC38189
Engine Capacity	: 5883 cc

The vehicle caught fire. The cause of fire probably due to Electrical. Right side of engine compartment. (Details see photographs enclosed)

In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as **“Total Loss”**.

Market Value	S\$	82,000.00 (est)
Less: LTA Reimbursement Value (RV)	(S\$	12,981.00)
Nett Liability	S\$	69,019.00
		=====

Vehicle Inspected By:



MUHD NAZRIL (NAZ)
Technical Investigator
LL.B. (Hons) London



K.K.LAU
MSc(Eng M), B Eng(Hons), PEng(UK),
MASME(USA), B Bus(Aust),MBA(UK),
IEng(UK), MIE(mech), MinstAEA, MFIEA,
MIRTE,MIMI,MSAE,MCIAd, AM,NIJAAR(USA),
AM CATARI(CAN),M.MATA(USA),M.MdATA(USA),
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.