



Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

Contact: 6773 7377 / 8778 3338

ROC NO. & GST REG NO.: (199806235M)

Page No. 1

Our Ref : UC375				
Vehicle No. : SMF7977A				
Make & Model : HONDA JAZZ 1.3 CVT				
QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(S\$)	SURVEYOR'S ADJUSTMENT
PARTS (LIST ITEMS)				
1	Rear bumper <i>cr</i>		493.00 ✓	
1	Rear bumper side retainer LH <i>?Xm</i>		25.00 X	
1	Front door LH <i>repair</i>		849.00 X	
1	Rear Fender (Repair refer to labor.)		0.00	
1	Rear door LH (Repair refer to labor.)		0.00	
493.00 20% 394.40			Part Items Total:	
			-20%	1367.00
				-273.40
				1093.60
SPECIAL NETT ITEMS				
1	Rear bumper clips <i>cr</i>		25.00 ✓	
25			SN Items Total:	25.00
Total Parts:				1118.60



Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

Contact: 6773 7377 / 8778 3338

ROC NO. & GST REG NO.: (199806235M)

Our Ref : UC375
Vehicle No. : SMF7977A
Make & Model : HONDA JAZZ 1.3 CVT

Page No. 2

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$)	SURVEYOR'S ADJUSTMENT
1	LABOUR To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components	800.00	300
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	1000.00	800
3	To remove and repair/refit wiring system at accident damaged area and check for all electrical proper function	90.00 X m	
4	To remove and refit/replace Front door LH fitting, trimmings, garnish, window glass and lock mechanism	120.00 X m	
5	To perform anti-rust treatment on affected areas	60.00 X m	
Labour Total :		2070.00	
TOTAL (PARTS & LABOUR):		3188.60	

394.40

25.00

1100.00

1519.40

20%

1215.52

4/5-1,200

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rashu

Hg 90010068

4 days

L/S

11/08/22 P1040

Resy after repair