

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

31-Mar-22

SUPPL ESTIMATE REPAIR BILL FOR HYUNDAI AVANTE REGN NO: SMP 1332 Y

1 pc	Rear bumper Lower moulding		\$	250.10	cut
		Less 20%	\$	50.02	
			\$	200.08	

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE
ANY UNFORESEEN DAMAGES.

278.48



F.P/P 798-48

RD : 2

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443
TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

ESTIMATE REPAIR BILL FOR HYUNDAI AVANTE REGN NO: SMP 1332 Y

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

Thivan@lhhauto.com
82235769

p/p repair 2 days sup

2430/3/22 1800

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: