



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2204925

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 10/08/2022
Reference CC3/CTI22002921/Tga3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SH 8304D
Insured Veh. SMP 830H
Claim No. SNM22D202068
Policy No. DMHCSNW00008452101
Accident Date 25/03/2022
Inspection Date 28/03/2022

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC3/CTI22002921/Tga3q2 Date: 10/08/2022 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SMP 830H	Veh. Inspected	SH 8304D	
Policy No.	DMHCSNW00008452101	Coverage (\$)	0.00	
Claim No.	SNM22D202068	Excess (\$)	0.00	
Assign From		Assign Date	28/03/2022	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI I40	c.c	1685	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	KMHLB41UMGU093286	Colour	BLUE	
Odometer	578552 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/60 R16	WEST LAKE	6 mm	
L/H Front Tyre	205/60 R16	WEST LAKE	6 mm	
R/H Rear Tyre	205/60 R16	WEST LAKE	6 mm	
L/H Rear Tyre	205/60 R16	WEST LAKE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	25/03/2022	Inspection Date	28/03/2022	
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			2 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SH 8304D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER COVER	DEFORMED	1,106.00	1,106.00
1	REAR BUMPER CLIPS	NECESSARY	22.00	22.00
2	REAR BUMPER BRACKET LH/RH @\$35.60	NOT NECESSARY	71.20	-
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	428.40	-
2	RR BUMPER REINFORCEMENT BRACKET LH RH @\$160.60	NOT NECESSARY	321.20	-
1	REAR BUMPER UNDER COVER	CUT	228.00	228.00
1	BOOTLID	BENT	2,174.90	2,174.90
1	BOOTLID 'H' EMBLEM	NECESSARY	63.10	63.10
1	BOOTLID CRDI PLATE	NECESSARY	52.40	52.40
1	BOOTLID MOULDING	NOT NECESSARY	85.00	-
1	BOOTLID I40 EMBLEM	NECESSARY	67.90	67.90
	LESS 20% DISCOUNT		-924.02	-742.86
			3,696.08	2,971.44
	<u>SPECIAL NETT ITEMS</u>			
1	REAR BUMPER ADVERTISEMENT LOGO (SN)	NECESSARY	50.00	50.00
1	BOOTLID ADVERTISEMENT LOGO (SN)	NECESSARY	100.00	100.00
1	REAR FENDER ADVERTISEMENT LOGO LH (SN)	NECESSARY	100.00	100.00
1	REAR FENDER ADVERTISEMENT LOGO RH (SN)	NECESSARY	100.00	100.00
1	REAR BUMPER REVERSE SENSOR (SN)	NOT WORKING	135.70	135.70
1	REAR BUMPER RUBBER MAT (SN)	NECESSARY	50.00	50.00
1	BOOTLID COMFORT LOGO & TEL NO.STICKER (SN)	NECESSARY	60.00	60.00
			595.70	595.70
	<u>LABOUR</u>			
	PANEL BEATING.		900.00	280.00
	SPRAY PAINTING CHARGE.		600.00	250.00
	CHECK ALL LIGHTING.	NOT NECESSARY	60.00	-
	REMOVE/REFIX REVERSE SENSOR .		60.00	30.00
			1,620.00	560.00
	GRAND TOTAL		5,911.78	4,127.14

Report Ref No. CC3/CTI22002921/Tga3q2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,300.00
---	--	--	----------

Report Ref No. CC3/CTI22002921/Tga3q2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SH 8304D

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SH 8304D

RE-INSPECTION

