

COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No. : SH8304D

Make : HYUNDAI

Model : I-40

Date: 28/03/2022

Insurance: CHINA TAIPING

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	REAR BUMPER COVER			\$ 1,106.00
1	REAR BUMPER CLIPS			\$ 22.00
2	REAR BUMPER BRACKET LH RH	\$	35.60	\$ 71.20
1	REAR BUMPER REINFORCEMENT			\$ 428.40
1	RR BUMPER REINFORCEMENT BRACKET LH RH	\$	160.60	\$ 321.20
1	REAR BUMPER UNDER COVER			\$ 228.00
1	BOOTLID			\$ 2,174.90
1	BOOTLID 'H' EMBLEM			\$ 63.10
1	BOOTLID CRDI PLATE			\$ 52.40
1	BOOTLID MOULDING			\$ 85.00
1	BOOTLID I40 EMBLEM			\$ 67.90
SUB TOTAL				\$ 4,863.90
LESS 20%				\$ 972.78
DISCOUNTED TOTAL				\$ 3,891.12
1	REAR BUMPER ADVERTISEMENT LOGO			\$ 50.00
1	BOOTLID ADVERTISEMENT LOGO			\$ 100.00
1	REAR FENDER ADVERTISEMENT LOGO LH			\$ 100.00
1	REAR FENDER ADVERTISEMENT LOGO RH			\$ 100.00
1	REAR BUMPER REVERSE SENSOR			\$ 135.70
1	REAR BUMPER RUBBER MAT			\$ 50.00
1	BOOTLID COMFORT LOGO & TEL NO. STICKER			\$ 60.00
Labour Charge				\$ 245.70
	PANEL BEATING			\$ 900.00
	SPRAY PAINTING CHARGE			\$ 600.00
	CHECK ALL LIGHTING			\$ 60.00
	REMOVE/REFIX REVERSE SENSOR			\$ 60.00
TOTAL LABOUR				\$ 1,620.00
ESTIMATE TOTAL				\$ 5,756.82

3714.30
 2971.49
 595.70
 280
 250
 30
 560
 4127.14
 45833.00
 2 days #

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company. The Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tamphi 97495749
 ins 28/3/22 @ 455
 4/5 Resurvey after repair
 tamphi@hikando.com
 2 days