

COI-FORTDELGRO PTE LTD

**REPAIR ESTIMATE\***

VEHICLE NO SHD4104S

DATE 3/26/22 12:00

MAKE REG.30.10.2022

MODEL : HYUNDAI IONIQ G3

CHIANG/CHINA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	FRONT BUMPER BRACKET RH		aut ✓	\$35.00 ✓
1	FRONT BUMPER		fr ✓	\$481.10 ✓
1	FRONT BUMPER CENTRE MOULDING		nn X	\$368.50
1	FRONT HEAD LAMP RH		aut ✓	\$2,110.30 ✓
1	FOG LAMP RH		nn X	\$642.50
1	FRONT FENDER RH		bt ✓	\$588.80 ✓
1	FRONT FENDER EMBLEM		neu ✓	\$26.60 ✓
1	FRONT BUMPER GARNISH RH		nn X	\$186.90
1	FRONT WHEEL COVER RH		aut ✓	\$346.40 ✓
	<b>SUB TOTAL</b>		3588.20	<b>\$4,786.10</b>
	<b>20.00%</b>			<b>\$957.22</b>
	<b>DISCOUNTED TOTAL</b>		2870.56	<b>\$3,828.88</b>
1	FRONT FENDER ADVERTISEMENT		100 neu ✓	\$100.00
	<b>Labour Charge</b>			<b>\$100.00</b>
	Panel Beating		350 ✓	\$600.00
	Spray Paint		500 ✓	\$600.00
	Reset Wheel alignment		940 ✓	\$60.00
	Check lighting		30 ✓	\$60.00
	<b>TOTAL LABOUR</b>			<b>\$1,320.00</b>
	<b>ESTIMATE TOTAL</b>		Q 3910.56 #	<b>\$5,248.88</b>
	<p>Tanpin 974952411</p> <p>UP 28/3/22 @ 445</p> <p>p/p using before paint</p> <p>2 days</p> <p>Tanpin Chhantaw</p>			
	<p>This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.</p>			

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: