

## COMFORT TRANSPORTATION PTE LTD

**REPAIR ESTIMATE**

Vehicle No. : SHA4494G

Make : HYUNDAI

Model : I-40

Date: 26/03/2022

Insurance: CHINA TAIPING

MVA: MS. Y Y

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	REAR BUMPER COVER			\$ 553.00
1	REAR BUMPER CLIPS			\$ 22.00
1	REAR BUMPER SIDE BRACKET RH			\$ 35.60
1	REAR BUMPER REFLECTOR LAMP RH			\$ 32.00
1	REAR BUMPER LOWER COVER			\$ 228.00
1	REAR BUMPER REINFORCEMENT			\$ 428.40
1	RR BUMPER REINFORCEMENT BRACKET RH			\$ 160.60
1	REAR BUMPER SPONGE			\$ 119.50
1	EXHAUST SILENCER RH			\$ 967.70
1	EXHAUST PIPE CENTRE			\$ 730.10
1	EXHAUST PIPE HANGER			\$ 117.10
	<b>SUB TOTAL</b>			\$ 3,394.00
	<b>LESS 20%</b>			\$ 678.80
	<b>DISCOUNTED TOTAL</b>			<b>\$ 2,715.20</b>
	REAR BUMPER ADVERTISEMENT LOGO			\$ 50.00
	REAR FENDER ADVERTISEMENT LOGO LH			\$ 100.00
	REAR FENDER ADVERTISEMENT LOGO RH			\$ 100.00
	REAR BUMPER REVERSE SENSOR			\$ 135.70
	REAR BUMPER RUBBER MAT			\$ 50.00
				<b>\$ 435.70</b>
	<b>Labour Charge</b>			
	PANEL BEATING			\$ 700.00
	SPRAY PAINTING CHARGE			\$ 300.00
	REMOVE/ REFIX EXHAUST PIPE			\$ 150.00
	REMOVE/ REFIX REVERSE SENSOR			\$ 60.00
	<b>TOTAL LABOUR</b>			<b>\$ 1,210.00</b>
	<b>ESTIMATE TOTAL</b>			<b>\$ 4,360.90</b>

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tanphu' 9249249  
 up' 26/3/22 8450/2  
 2 days  
 45 days after repair  
 Tanphu' @ 11h40 to 11h50

- Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
  - To display damaged part(s) during resurvey
  - Parts prices are subject to confirmation
  - Third party survey is on a "Without Prejudice" basis
  - No illegal modification(s) is allowed
  - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature: