

COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No. : SH7916U

Make : HYUNDAI

Model : I-40

Date: 25/03/2022

Insurance: CHINA TAIPING

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	REAR BUMPER COVER			\$ 1,106.00
1	REAR BUMPER CLIPS			\$ 22.00
1	REAR BUMPER REINFORCEMENT			\$ 428.40
2	RR BUMPER REINFORCEMENT BRACKET RH LH		\$ 160.60	\$ 321.20
1	REAR BUMPER UNDER COVER			\$ 228.00
1	BOOTLID		2174.90	\$ 2,609.48
1	BOOTLID 'H' EMBLEM			\$ 63.10
1	BOOTLID CRDI PLATE			\$ 52.40
1	BOOTLID I40 EMBLEM			\$ 67.90
1	LICENSE LAMP			\$ 56.10
1	REAR PANEL			\$ 526.70
1	REAR PANEL GARNISH			\$ 57.70
1	EXHAUST SILENCER LH			\$ 967.70
1	EXHAUST PIPE CENTRE			\$ 730.10
1	EXHAUST PIPE HANGER			\$ 117.10
	SUB TOTAL		3714.30	\$ 7,353.88
	LESS 20%			\$ 1,470.78
	DISCOUNTED TOTAL		2971.44	\$ 5,883.10
	BOOTLID ADVERTISEMENT LOGO			\$ 100.00
	BOOTLID CITYCAB LOGO & TEL NO STICKER			\$ 60.00
	REAR BUMPER REVERSE SENSOR			\$ 135.70
				\$ 295.70
	Labour Charge			
	PANEL BEATING			\$ 900.00
	SPRAY PAINTING CHARGE			\$ 750.00
	CHECK ALL LIGHTING			\$ 60.00
	TUFF KOTE			\$ 60.00
	REMOVE/REFIX REVERSE SENSOR			\$ 60.00
	TOTAL LABOUR			\$ 1,830.00
	ESTIMATE TOTAL			\$ 8,008.80

Tanpin 9749545
 WP, 20/3/22 @ 440
 23 days
 c/s Resurvey after repair
 Tanpin @ 11hamp.com

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: