

Lian Her Motors

Blk 5038 #01-405 Ang Mo Kio Industrial Pk 2 Singapore 569541
Tel : 64817221

L H Car Rental Pte Ltd
Blk 5038 #01-405
Ang Mo Kio Industrial Pk 2
Singapore 569541

Vehicle No : SLU 9192 S
Make : Toyota C-HR
Year : 2017

Fax : 64816131

*Not Authorized
L/Ry @ 1500p
Permy After Pain
2 days*

Qty	Description	Unit Price	Amount
-----	-------------	------------	--------

Estimate Cost Of Repair

1 pc	Rear bumper	855.10
1 pc	Rear bumper reinforcement	382
1 pc	Rear lower bumper	465.10
2 pcs	Rear bumper side retainer	
1 pc	Rear end panel	

	Per	\$875.60	✓
	By	\$483.20	✓
	Ref	\$550.60	✓
\$75.10	Sm	\$150.20	X
	R	\$725.70	X
		\$2,785.30	
Less 25 %		\$696.33	
		\$2,088.97	

S Nett

15 pcs	Rear bumper clip	
1 pc	Rear reverse sensor	

\$2.00	Per	\$30.00	✓
	Ref	\$200.00	✓

Labour Charges

Remove/renew the above parts including knocking, welding & cutting.

200p
\$600.00

To putty & spray paint on accident affected portion

200p
\$500.00

Check and reconnect wiring

15p
\$40.00
Total \$3,458.97

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: