

AERO GARAGE PTE LTD

Blk 160, Sin Ming Drive, #08-07 Sin Ming AutoCity, Singapore 575722

Tel : 6266 9511 Fax : 6266 9512

Vehicle No : SMM8699J
Vehicle Model : Honda Freed

Estimate Repair Cost

No.	Qty	Parts List Items		
1	1	Front bumper ✓ CRA	\$	628.90 ✓ 510 /
2	2	Front bumper retainers ✓ DE	\$	46.80 ✓ 38 /
3	2	Front bumper brackets ✓ CRA	\$	89.80 ✓ 58 /
4	1	Front bumper reinforcement ✓ BR	\$	468.00 ✓ 260 /
5	1	Front bumper centre grille X NN	\$	175.50
6	1 2	Front bumper tow covers ✓ CUT	\$	57.60 25.6 20 /
7	1 set	Front bumper clips ✓ NEC	\$	40.00 ✓ 32 /
8	1	Front bonnet ✓ BT	\$	780.80 720.8 420 /
9	1	Front bonnet insulator ✓ DE	\$	107.30 ✓ 75 /
10	2	Front bonnet hinges ✓ BT	\$	148.20 91.2 90 /
11	1	Front bonnet inner lock ✓ BT	\$	165.80 ✓ 165 /
12	1	Front bonnet cable X NN	\$	49.60
13	1	Front grille ✓ CRA	\$	1,072.50 750.9 510 /
14	2	Head lamps ✓ DIS	\$	3,432.40 ✓ 1660 /
15	2	Front fenders ✓ BUC	\$	1,289.00 880 580 /
16	2	Front fender inner shields X NN	\$	65.20
17	1	Front support panel ✓ DIS	\$	741.50 ✓ 470 /
18	1	Radiator ✓ BT	\$	1,657.50 1502.7 740 /
19	1	Radiator fan motor ✓ NW	\$	347.60 301.8 200 /
20	1	Radiator fan cover ✓ BR	\$	132.60 125.8 60 /
21	1	Radiator fan blade ✓ JM	\$	64.60 ✓ 58 /
22	1	Air condenser ✓ BT	\$	861.90 ✓ 630 /
23	1	Air condenser fan motor ✓ NW	\$	228.70 ✓ 175 /
24	1	Air condenser fan blade ✓ JM	\$	58.90 ✓ 55 /
25	1	Wiper washer tank ✓ DE	\$	74.90 ✓ 50 /
26	1	Hom X NN	\$	74.10
Total			\$	12,859.70 11388.3

Parts Disc -20%: 9110.64

Parts Special Nett Items

27	1	Front number plate ✓ MIS	\$	60.00 40
			\$	60.00
Total Parts			\$	12,919.70

Labour

1	Labour charge to remove, cut out damage portion, jack out, straighten, panel beating, welding, align and renew replaced parts.	\$ 1,500.00 600
2	To putty and respray painting on affected areas.	\$ 1,200.00 1000
3	To remove, replace front bonnet and fenders fittings to facilitate repair.	\$ 500.00 50
4	To remove, replace radiator and air condenser fan assy.	\$ 300.00 120
5	To remove, replace front horn.	\$ 150.00 X NN
6	To check wiring and lightings.	\$ 80.00 30

Total Labour \$ 3,730.00 1800

Total Parts and Labour \$ 16,649.70

5 Days

Total: 11286.64

Part by part repair

Before paint photos

After repair photos

Excess: TBA

Not Authorised

Guo Qiang - LKK

HP: 82880282

GuoQiang@lkkauto.com

31/03/2022

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

AERO GARAGE PTE LTD

Blk 160, Sin Ming Drive, #08-07 Sin Ming AutoCity, Singapore 575722

Tel : 6266 9511 Fax : 6266 9512

Vehicle No : SMM8699J
Vehicle Model : Honda Freed

Supplementary List

No.	Qty	<u>Parts List Items</u>			
1	1	Manifold intake ✓ CRA	\$	410.00 320	410 ✓
2	1	Manifold sensor ✓ CRA	\$	200.00 100	200 ✓
Total :			\$	610.00 420	
				-20%: 336	