

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22002935/VQY3M4**Date:** 01/07/2022REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00105682101

Claimant Vehicle No : GBA2586J **Insured Vehicle No :** SLD8560J

Date of Loss: 23/03/2022 Nature of Claim: TP Claim No: SNM22D202038/C02/LEWLC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBA2586J**

Make & Model: TOYOTA DYNA 1.5T, 3.0 (M) Engine No: 1KD1623959

Reg. Date: 02/05/2007 (Man. Year: 2007) Chassis No: JTFAT35Y103000753

Colour: White Odometer: 90206 km

Engine Capacity: 2982 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 195 R15C Rear Tyre Size: 195 R15C

Front Left Side: Michelin 5 mm Rear Left Side: Michelin 5 mm

Front Right Side: Michelin 5 mm Rear Right Side: Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,846.56	1,993.26	1,853.30	48.18
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,760.00	560.00	1,200.00	68.18
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,606.56	2,553.26	3,053.30	54.46
Approved Total (Overridden) (S\$)		2,050.00		
(S\$)	5,606.56	2,050.00	3,556.56	63.44
+ GST 7.00/7.00% (S\$)	392.46	143.50	248.96	63.44
Nett Amount (S\$)	5,999.02	2,193.50	3,805.52	63.44

INSPECTION

Date of Assignment: 30/03/2022

Date Inspected: 27/05/2022 Inspected At: Hs Automotives Pte Ltd (HQ)
BLK 2 KAKI BUKIT AVE 2, #02-25
Singapore 417921

Estimated Period of Repair: 3.0 days

Adjuster: Thevan Thomas Karthikesavan**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 01 Jul 2022)	
Parts:	N/A	TOYOTA DYNA 1.5T 3.0 (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBA2586J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RH DOOR	Dented	1,680.23 F	*1,350.00 FL
2	1		*RH DOOR OUTER HANDLE	Dented	210.02 F	*210.02 FL
3	1		*RH DOOR LOCK	Jammed	509.23 F	*250.00 FL
4	1		*RH DOOR TOP MOULDING	Necessary	168.23 F	*168.23 FL
5	1		*RH DOOR INNER MOULDING	Necessary	201.23 F	*201.23 FL
6	1		*RH DOOR FRAME RUBBER	Deformed	223.07 F	*223.07 FL
7	2		*RH DOOR HINHE TOP / BOTTOM	Dented	148.46 F	*148.46 FL
8	1		*RH DOOR INNER BOARD	Serviceable	606.09 F	*- FL
9	1		*RH DOOR INNER BOARD CLIP	Necessary	50.00 FS	*30.00 FS
10	1		*RH DOOR STICKER (COMPANY)	Necessary	50.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	3,846.56	2,631.01
- List Item Discount on L Items 0.00/25.00% (\$)	0.00	637.75
Total Parts (\$)	3,846.56	1,993.26

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEAT	New	800.00	300.00
2	RESPRAY PAINT	New	800.00	200.00
3	RUST PROOF	New	80.00	30.00
4	CHECK WIRING	New	80.00	30.00
			Gross Labour Cost (\$\$)	560.00
			1,760.00	1,760.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >