

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No.: 6287 6666 Fax No.: 6257 1330

CO./GST Reg. No. 201019626G

SHD9773C

AAD2203-104

Not Authored

Resony B4 paint

82687.78

Vehicle No.:
Chassis No.:
Company UEN No.:
Vehicle Make:
Vehicle Model:
Date of Accident :
Third Party Insurer :
Date of Registration:

29 MAR 2022

SHD9773C

JTDKB3FU503093224

200303878K

TOYOTA

PRIUS **GEN 4**

25/3/2022

SFY3288P / CHINA TAIPING

23/12/2020

PART	LIST
1 COVER, REAR BUMPER	\$ Bu 485.60 ✓
1 REINFORCEMENT SUB-ASSY, REAR BUMPER	\$ B 332.70 ✓
1 COVER, REAR BUMPER, LOWER	\$ B 22.00 ✓
1 GUARD, REAR BUMPER, CENTER	\$ B 374.50 ✓
1 RETAINER, REAR BUMPER SIDE, LH	\$ Su 132.60 X
1 RETAINER, REAR BUMPER SIDE, RH	\$ Su 132.60 X
1 REFLECTOR ASSY, REFLEX, LH	\$ Su 39.00 X
1 REFLECTOR ASSY, REFLEX, RH	\$ Su 39.00 X
1 LENS & BODY, REAR COMBINATION LAMP, LH (Upper)	\$ Su 339.60 X
1 LENS & BODY, REAR COMBINATION LAMP, RH (Upper)	\$ Su 339.60 X
1 LENS & BODY, REAR COMBINATION LAMP, NO.2 LH (Lower)	\$ Su 261.00 X
1 LENS & BODY, REAR COMBINATION LAMP, NO.2 RH (Lower)	\$ Su 261.00 X
1 LAMP ASSY, REAR, LH (Back Door)	\$ Su 293.60 X
1 LAMP ASSY, REAR, RH (Back Door)	\$ Su 293.60 X
1 PANEL SUB-ASSY, BACK DOOR	\$ R 1,147.80 X
1 PLATE, LUGGAGE COMPARTMENT DOOR NAME, NO.2	\$ R 54.60 ✓
1 PLATE, BACK DOOR NAME, NO.1	\$ R 54.60 ✓
1 ORNAMENT SUB-ASSY, BACK DOOR	\$ R 47.90 ✓
1 GARNISH SUB-ASSY, BACK DOOR, OUTSIDE	\$ Su 913.60 X
1 BOARD ASSY, BACK DOOR TRIM	\$ Su 259.20 X
1 WEATHERSTRIP, BACK DOOR	\$ Su 372.30 X
1 PAN, REAR FLOOR	\$ R 583.40 X
1 COVER, FLOOR UNDER, NO.1 LH	\$ Su 175.10 X
1 COVER, FLOOR UNDER, NO.2 RH	\$ Dis/cmt Su 241.90 ✓
1 COVER, REAR FLOOR CTR	\$ Bu 229.90 ✓
1 COVER, DECK TRIM, REAR	\$ Su 126.70 X
1 LOCK ASSY, BACK DOOR, W/COURTESY LAMP SWITCH	\$ Su 467.00 X
1 PANEL SUB-ASSY, BODY LOWER BACK	\$ R 651.00 X
1 PIPE ASSY, EXHAUST, TAIL	\$ R 1,649.00 X

Trans-cab Auto Services Pte Ltd

AAD2203-104

No. 2 Ang Mo Kio Street 63 Singapore 569111
 Tel No. : 6287 6666 Fax No. : 6257 1330
 CO./GST Reg. No. 201019626G

SHD9773C

TOTAL	\$	10,320.40
25%	\$	2,580.10
	\$	7,740.30

Special Nett

1SET PARKING AID	\$	<i>pd/boat</i> 700.00	<i>2205m</i>
1SET REAR BUMPER CLIP	\$	<i>na</i> 95.00	<i>605m</i>
2 WINDSCREEN SEALANT	\$	<i>na</i> 150.00	} <i>X</i>
1 WINDSCREEN MOULDING	\$	<i>na</i> 200.00	
1 WINDSCREEN INNER SPONGE SEAL	\$	<i>na</i> 130.00	
1 REAR BUMPER PROTECTOR	\$	<i>na</i> 180.00	
1SET REAR BUMPER RETAINER CLIP	\$	<i>na</i> 85.00	
1 END PANEL TRIM CLIP	\$	<i>na</i> 65.00	
1SET BUMPER CLIP FRT	\$	<i>na</i> 95.00	
1 REAR NUMBER PLATE WITH MOULDING	\$	<i>pa</i> 200.00	

TOTAL	\$	1,900.00
--------------	-----------	-----------------

TOTAL PARTS	\$	9,640.30
--------------------	-----------	-----------------

LABOUR

To Remove And Refit Rear Big and Small W/Screen Glass To Facilitate Bodywork Repair.	\$	<i>na</i> 300.00	<i>X</i>
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>na</i> 380.00	<i>X</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	2,500.00	<i>3001</i>
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	<i>na</i> 380.00	<i>X</i>
To transfer of Tailgate fittings, attachments and perform water seepage test.	\$	<i>na</i> 280.00	<i>X</i>

Trans-cab Auto Services Pte Ltd

AAD2203-104

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9773C

To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	<i>na</i>	250.00	X
Putty And Spray Painting Of The Affected Portion.	\$		2,200.00	<i>6601</i>
To reinstall rear bumper parking sensor.	\$		170.00	<i>301</i>
To Check Electrical Lighting Concerned.	\$		170.00	<i>151</i>
To transfer of luggage floor panel fittings, attachment and perform water seepage test.	\$	<i>na</i>	380.00	X
To transfer of tire, rim and on wheel balancing.	\$	<i>na</i>	220.00	X

TOTAL	\$	7,230.00
--------------	-----------	-----------------

Over All Total	\$	16,870.30
-----------------------	-----------	------------------

(PART-BY-PART) Repair Days**10 DAYS***3 days*

- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: