

Brew Bikes UEN53431371W Blk 261 Waterloo St, #01-42, Singapore 180261

RE: BIKE ASSESSMENT REPORT

To Whom It May Concern,

After assessing the bicycle, damages were found on the following items that were damage during an accident. It had to be replaced with new components as it's beyond repair.

- 1. Canyon Speedmax CF Frameset

 ✓ BT

 \$5391.72
- 2. Canyon Speedmax CF handlebar (inclusive with frameset pricing) VBT
- 3. Shimano Dura-ace Shifter set (Time Trial) / DIS
- 4. Shimano Dura-ace brake level set ✓ JM
- 5. Assioma Favero power meter ✓ NW
- 6. Shimano Pedals V BT —— \$1006.75
- 7. Helmet ✓ CRA \$442.03

Total: 6840.5

It has also been reported that due to the impact of the accident, the cyclist helmet has also been damage and it had to be replaced due to the integrity has been jeopardise.

We are unable replace certain items on the list. Please refer to the invoices provided by the owner cost/purchase price.

Best Regards,

Kelvin Ng Brew Bikes

<u>sales@webrewbikes.com</u> <u>www.webrewbikes.com.sg</u>

M: +65 9168 8986

LKK Auto Consultants hence notify
the Repairer of the following:

• To resurvey betorstailer apray painting

• To display damaged part(s) during resurvey

• Parts prices are subject to confirmation

• Third party survey is on a "Without Projudice" basis

• No liegal modification(s) is allowed

• Supplementary item(s) must be resurveyed and
is subject to final approved from insurance Company

Acknowledged by Repairer

Signature:
Code: