

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : KAO JIA YU ANGELINA
21 BERWICK DRIVE

Singapore 559911

ATTN:

Estimate No: MC1902554
Date: 29 Mar 2022
Policy No: 10991666
Veh Reg No: SLV9339G
Make/Model: LAND ROVER
DISCOVERY SPORT 2.0P

Your Ref No: SLV9339G
Claim Type: Third Party
Accident Date: 23/03/2022
TP Veh Reg No: GBH9614D

Estimate Repair Cost to Vehicle No :SLV9339G

Description	Quantity	List Price S\$	Amount S\$
SPARE PARTS			
1 FRONT DOOR LH	1 PC	3,450.45	
2 FRONT DOOR RUBBER (AT DOOR) LH	1 PC	254.70	
3 FRONT DOOR GLASS LH	1 PC	580.95	
4 FRONT DOOR GLASS OUTER MLDG LH	1 PC	233.90	
5 FRONT DOOR GLASS OUTER MLDG TOP LH	1 PC	356.50	
6 SIDE MIRROR LH	1 PC	1,173.57	
7 SIDE MIRROR COVER LH	1 PC	212.80	
8 SIDE MIRROR SIGNAL LAMP LH	1 PC	241.56	
9 SIDE MIRROR GLASS LH	1 PC	357.87	
10 SIDE MIRROR BLIND SPOT MIRROR LH - CHECK PRICE	1 PC	0.00	
11 SIDE MIRROR LAMP EXTERIOR MIRROR	1 PC	248.85	
12 SIDE MIRROR MOTOR	1 PC	394.71	
13 SIDE MIRROR PLUG	1 PC	28.35	
		7,534.21	
	Less 10%	753.42	6,780.79
Special Nett			
14 FRONT DOOR GLASS SOLAR FILM	1 PC	200.00	
		200.00	200.00
LABOUR			
15 TO DISMANTLE AND TRANSFER DOOR FITTINGS AND MECHANISM SUCH AS POWER WINDOW MOTOR AND REGULATOR TO NEW DOOR/FACILITATE REPAIR.	1 PC	80.00	
16 TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD . TO KNOCK & REPAIR INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	400.00	
17 TO SPRAY FRONT DOOR LH,SIDE MIRROR LH.	1 PC	450.00	
		930.00	930.00

Zila
Ah Lim Motor Company

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : KAO JIA YU ANGELINA
21 BERWICK DRIVE

Singapore 559911

ATTN:

Estimate No: MC1902554
Date: 29 Mar 2022
Policy No: 10991666
Veh Reg No: SLV9339G
Make/Model: LAND ROVER
DISCOVERY SPORT 2.0P

Your Ref No: SLV9339G
Claim Type: Third Party
Accident Date: 23/03/2022
TP Veh Reg No: GBH9614D

Estimate Repair Cost to Vehicle No :SLV9339G


Description	Quantity	List Price S\$	Amount S\$
Total			S\$ 7,910.79
Add GST @ 7%			553.76
Total Amount Payable			S\$ 8,464.55

TOTAL: SINGAPORE DOLLAR EIGHT THOUSAND FOUR HUNDRED SIXTY FOUR AND CENTS FIFTY FIVE ONLY

Please arrange this vehicle to be surveyed soonest possible.

Thank You

For AH LIM MOTOR COMPANY


Zila
Ah Lim Motor Company
AUTHORISED SIGNATURE

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	856B

Vehicle Details

Vehicle No.:	SLV9339G
Vehicle to be Exported:	No
Intended Deregistration Date:	30 Mar 2022
Vehicle Make:	LAND ROVER
Vehicle Model:	DISCOVERY SPORT 2.0P 7 SEATER S/R
Primary Colour:	Grey
Manufacturing Year:	2017
Engine No.:	171121Y0613PT204
Chassis No.:	SALCA2AX8JH745740
Maximum Power Output:	177.0 kW (237 bhp)
Open Market Value:	\$46,683.00
Original Registration Date:	25 Jan 2018
First Registration Date:	25 Jan 2018
Transfer Count:	1
Actual ARF Paid:	\$57,357.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	24 Jan 2028
PARF Rebate Amount:	\$43,017.00

Intended COE Rebate Details

COE Expiry Date:	24 Jan 2028
COE Category:	E - Open - all except motorcycle
COE Period(Years):	10
QP Paid:	\$48,011.00
COE Rebate Amount:	\$27,342.00
Total Rebate Amount:	\$70,359.00

The information contained herein is correct as at 29 Mar 2022

OK