

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SNA 4883 X

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WAHSEY ASSY AND FRONT PARKING AID.	S/N \$ 480.00 /	✓
2	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 400.00 250	✓
3	TO REMOVE AND RENEW AIRCON CONDENSER, CHARGE AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT.	S/N \$ 1,700.00 /	✓
4	TO CARRY OUT PRESSURISE, VACUUM AND REGAS FOR R1234.	S/N \$ 1,200.00 /	✓
5	TO DISMANTLE LHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL LHS WING MIRROR ASSY TO FACILITATE RESPRAYING OF LHS FRONT DOOR.	S/N \$ 280.00 /	✓
6	TO RENEW LHS FRONT FENDER INNER AIRCON PIPE.	S/N \$ 280.00 7	✓
SUB TOTAL LABOUR CHARGES		: \$ 4,340.00	

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NOPA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SNA 4883 X

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
7	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, LHS FRONT FENDER AND LHS HEADLIGHT. TO REPAIR LHS FRONT DOOR AND LHS UPPER A-PILLAR. TO CUT OUT AND WELD LHS FRONT FENDER TOP SUPPORT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 8,800.00	4000 ✓
8	TO RESPRAY FRONT BUMPER, BONNET HINGES, LHS FRONT FENDER, LHS FRONT FENDER TOP SUPPORT, LHS UPPER A-PILLAR AND LHS FRONT DOOR.	\$ 5,500.00	3925 ✓
9	TO TOW BACK THE VEHICLE FROM ACCIDENT SCENE.	S/N \$ 280.00	X
10	TO RENEW LHS FRONT RIM. TO CARRY OUT PRE/POST WHEEL ALIGNMENT.	S/N \$ 520.00	280 X
11	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK.	S/N \$ 384.00	✓
TOTAL LABOUR CHARGES		: \$ 19,824.00	

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NDRA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNA 4883 X

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
1	FRONT BUMPER / BR	1	\$ 2,493.00	/ 1994.4
2	FRONT BUMPER SECURING STRIP - BT	2	\$ 79.00	/ 63.2
3	FRONT BUMPER GRILLE - CENTER ? / BR	1	\$ 219.00	/ 174.8
4	FRONT BUMPER CLOSING ELEMENT - LOWER CENTER ? / BR	1	\$ 293.00	/ 234
5	FRONT BUMPER AIR GUIDE - LH / BR	1	\$ 72.00	/ 57.2
6	FRONT BUMPER CLOSING ELEMENT ? / CR4	1	\$ 293.00	/ 234
7	FRONT BUMPER AIR GUIDE GRILLE - LH / RH / MS	1	\$ 151.00	/ 120.4
8	FRONT BUMPER TRIM - LH / RT	1	\$ 54.00	/ 42.64
9	RADIATOR GRILLE TRIM - CENTER ? X nn	1	\$ 127.00	
10	RADIATOR GRILLE / BR	1	\$ 1,881.00	/ 1504.8
11	RADIATOR GRILLE BRACKET ? X nn	1	\$ 19.00	
12	RADIATOR GRILLE CAP COVER X nn	1	\$ 141.00	
13	FRONT BUMPER FOAM FILLER PIECE / BR	1	\$ 163.00	/ 130.4
14	FRONT BUMPER REINFORCEMENT BEAM / nn	1	\$ 899.00	/ 719.2
15	FRONT BUMPER GUIDE SECTION - LH / BR	1	\$ 41.00	/ 32.24
16	FRONT BUMPER BRACKET - LH ? / BR	1	\$ 254.00	/ 203.2
17	FRONT BUMPER TOP COVER / BR	1	\$ 143.00	/ 114
18	CAUTION STICKER / ne	1	\$ 16.00	/ 12.4
19	AIR COND STICKER / ne	1	\$ 9.00	/ 6.64
20	FRONT BUMPER LOCK CARRIER BRACKET / BR	1	\$ 154.00	/ 122.8
SUB TOTAL SPARE PARTS		:	\$ 7,501.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNA 4883 X

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT BUMPER SUPPORT - LH / RH <i>nc</i>	2	\$ 64.00 /	51.04
22	POP RIVET <i>nc</i>	4	\$ 4.00	
23	FRONT PARKING AID SENSOR - INNER / OUTER <i>? x nn</i>	2	\$ 530.00	
24	FRONT PARKING AID SENSOR SIDE <i>? x nn</i>	1	\$ 265.00	
25	FRONT PARKING AID SENSOR SEAL RING <i>nc x nn</i>	6	\$ 15.00	
26	FRONT BUMPER WIRING SET <i>? / TN</i>	1	\$ 449.00 /	358.8
27	HORN - LH <i>CR4</i>	1	\$ 134.00 /	106.8
28	HORN SUPPORT - LH <i>BT</i>	1	\$ 33.00 /	25.68
29	FRONT FENDER - LH <i>nn</i>	1	\$ 1,189.00 /	951.2
30	FRONT FENDER ATTACHMENT PARTS <i>x nn</i>	1	\$ 55.00	
31	FRONT FENDER CLOSING ELEMENT - LH <i>nc</i>	1	\$ 83.00 /	65.84
32	FRONT FENDER BRACKET - LH <i>BT</i>	1	\$ 41.00 /	32.72
33	FRONT FENDER POP RIVET <i>nc</i>	5	\$ 19.00 /	15.2
34	FRONT FENDER BRACKET CENTER - LH <i>? / BT</i>	1	\$ 55.00 /	44
35	FRONT FENDER BRACKET CENTER - LH <i>? x nn</i>	1	\$ 40.00	
36	FRONT FENDER BRACKET END - LH <i>? x nn</i>	1	\$ 65.00	
37	FRONT FENDER HOLE COVER - LH <i>x nn</i>	1	\$ 20.00	
38	FRONT FENDER CLOSING ELEMENT - LH <i>? x nn</i>	1	\$ 37.00	
39	FRONT FENDER BRACE - LH <i>nn</i>	1	\$ 132.00 /	105.2
40	FRONT WHEEL HOUSING LINER - LH <i>mis</i>	1	\$ 299.00 /	238.8
SUB TOTAL SPARE PARTS		:	\$ 3,529.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNA 4883 X

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
41	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS <i>X nn</i>	1	\$ <i>APK</i>	176.00	
42	FRONT WHEEL SPOILER - LH <i>/ mis</i>	1	\$	82.00 <i>/</i>	65.12
43	FRONT WHEEL SPOILER LOWER - LH <i>/ mis</i>	1	\$	39.00 <i>/</i>	31.12
44	FRONT WHEEL SPOILER STONE CHIP GUARD - LH <i>X nn</i>	1	\$	57.00	
45	FRONT WHEEL SPOILER TRIM BRACKET - LH <i>? X nn</i>	1	\$	27.00	
46	BONNET <i>/ nn</i>	1	\$	3,491.00 <i>/</i>	2792.8
47	BONNET HINGE - LH / RH <i>? X nn</i>	2	\$	932.00	
48	BONNET IMPACT PROTECTION - CENTER / LH / RH <i>/ ne</i>	3	\$	93.00 <i>/</i>	73.2
49	BONNET SOUND ABSORBER <i>/ CRH</i>	1	\$	382.00 <i>/</i>	305.6
50	FRONT FENDER LEDGE COVER - LH <i>? X nn</i>	1	\$	81.00	
51	FRONT FENDER LEDGE COVER - LONG <i>? / dec</i>	1	\$	40.00 <i>/</i>	31.44
52	FRONT FENDER LEDGE COVER - SHORT <i>? X nn</i>	1	\$	18.00	
53	HEADLAMPS COVER - LH <i>/ RR</i>	1	\$	49.00 <i>/</i>	38.64
54	BONNET STRIKER <i>(LH) RH / BT</i>	1 <i>2</i>	\$	112.00 <i>14-56 /</i>	44.56
55	BONNET LOCK <i>/ BT</i>	1	\$	223.00 <i>/</i>	182
56	BONNET BOWDEN CABLE - CENTER <i>? X nn</i>	1	\$	64.00	
57	BONNET RELEASE LEVER <i>? X nn</i>	1	\$	11.00	
58	BONNET RELEASE LEVER <i>? X nn</i>	1	\$	15.00	
59	BONNET LOCK CABLE <i>? X nn</i>	1	\$	82.00	
60	PLENUM CHAMBER COVER <i>X nn</i>	1	\$	108.00	
SUB TOTAL SPARE PARTS		:	\$	6,087.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNA 4883 X

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
61	HEADLIGHT MATRIX BEAM - LH / GR	1	\$ 8,172.00	6537.60
62	HEADLIGHT HOSE ? X nn	1	\$ 42.00	
63	SPACER ? / BT	3	\$ 136.00	107.84
64	LIFT CYLINDER - LH / MIS	1	\$ 217.00	173.6
65	LIFT CYLINDER BRACKET - LH / MIS	1	\$ 17.00	12.88
66	LIFT CYLINDER CORRUGATED PIPE / TH	1	\$ 107.00	85.60
67	LOCK CARRIER / GR	1	\$ 1,127.00	901.6
68	LOCK CARRIER SUPPORT - LH / RH ? X nn	2	\$ 85.00	
69	A/C CONDENSER ? X nn	1	\$ 683.00	
70	REFRIGERANT LINE ? / BT	1	\$ 186.00	148.8
71	REFRIGERANT LINE ? X nn	1	\$ 381.00	
72	REFRIGERANT LINE ? / BT	1	\$ 277.00	221.6
73	REFRIGERANT PIPE ? / BT	1	\$ 585.00	468
74	REFRIGERANT LINE BRACKET ? X nn	1	\$ 9.00	
75	OUTSIDE TEMPERATURE SENSOR BRACKET / MC	1	\$ 21.00	16.32
76	CHARGE AIR COOLER ? X nn	1	\$ 654.00	
77	PRESSURE PIPE ? X nn	1	\$ 496.00	
78	RADIATOR ? X nn	1	\$ 699.00	
79	RADIATOR FAN RING ? X nn	1	\$ 277.00	
80	RADIATOR FAN CONTROL UNIT ? X nn	1	\$ 2,012.00	
SUB TOTAL SPARE PARTS		:	\$ 16,183.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNA 4883 X

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
81	RADIATOR AIR GUIDE OUTER - LH / RH ? X nn	2	\$	72.00	
82	RADIATOR AIR GUIDE INNER - LH / RH ? X nn	2	\$	38.00	
83	RADIATOR AIR GUIDE - UPPER ? X nn	1	\$	19.00	
84	RADIATOR AIR GUIDE - LOWER ? X nn	1	\$	25.00	
85	RADIATOR COOLANT / nec	6	\$	282.00	225.6
86	FRONT FENDER CHROME TRIM - LH / nec	1	\$	171.00	136.4
87	FRONT DOOR CHROME TRIM - LH / nec	1	\$	171.00	136.4
88	FRONT DOOR WINDOW SLOT SEAL TRIM STRIP - LH X nn	1	\$	446.00	
89	FRONT WINDSCREEN WATER DEFLECTOR STRIP - LH X nn	1	\$	75.00	
90	ROOF MOLDING - LH X nn	1	\$	706.00	
91	ALUMINIUM RIM / FWT X nn	1	\$	1,889.00	
92	RUBBER VALVE X nn	1	\$	4.00	
93	FRONT FENDER CONNECTING PLATE UPPER - LH / BT	1	\$	279.00	222.8
94	FRONT FENDER CONNECTING PLATE - LH / BT	1	\$	241.00	192.4
95	FRONT NO PLATE / nec	S/N	\$	60.00	60
96	ARYLIC SEALANT / nec	S/N	\$	180.00	180
97	CAVITY WAX / nec	S/N	\$	140.00	140
98	STONE CHIP X nn	S/N	\$	180.00	
99	METAL FILLER POWDER / nec	S/N	\$	280.00	280
100	SUNDRIES ? / nec		\$	500.00	56 / 56
TOTAL SPARE PARTS			:	\$	39,058.00
TOTAL LABOUR CHARGES			:	\$	19,824.00
GRAND TOTAL			:	\$	58,882.00

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: norah.khai@premium-auto.com.sg / claims@premiumauto.com.sg

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

Steve (LKK)
29/3/11, 12.00pm

OD- M ML
Exp 11 - ?

PIP

by RL by
12 days

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT