



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CS/FCI22002949/Rqy3s2	
			Date: 22/04/2022	
			Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SML 2071P	Veh. Inspected	SNE 5287P
	Policy No.		Coverage (\$)	0.00
	Claim No.	D22000915MVQC	Excess (\$)	0.00
	Assign From	HARMINDER	Assign Date	30/03/2022
2. Vehicle Particulars & Condition				
	Make & Model	MERCEDES BENZ CLA180 CP	c.c	1332
	Engine No.	HIDDEN	Year of Reg.	2022
	Chassis No.	W1K1183842N286589	Colour	BLACK
	Odometer	326 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	225/45 R18	HANKOOK	6 mm
	L/H Front Tyre	225/45 R18	HANKOOK	6 mm
	R/H Rear Tyre	225/45 R18	HANKOOK	6 mm
	L/H Rear Tyre	225/45 R18	HANKOOK	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	27/03/2022	Inspection Date	05/04/2022
	Survey held at	CYCLE & CARRIAGE INDUSTRIES PL 188 PANDAN LOOP SINGAPORE 128378 (MERCEDES-BENZ)		
5a. Remarks				
	A)DAMAGES CONSISTENT TO ACCIDENT REPORT B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	