



Mercedes-Benz

Finalization

Cycle & Carriage  
Industries Pte Limited  
Authorised Dealer  
Company No. 196400367W  
GST Reg No. MR-8500111-X

## ESTIMATE FOR SNE5287P

MS FIRST CAPITAL INSURANCE LIMITED

MOTOR CLAIM DEPARTMENT  
6 RAFFLES QUAY  
#21-00  
SINGAPORE 048580  
65073848

### Vehicle & Document Information

WIP No **55855**  
Reg No/Reg Date **SNE5287P / 23/03/2022**  
Date In/Mileage **05/04/2022 / 326**  
Chassis No **W1K1183842N2865890**  
Engine No **28291480770390**  
Make/Model **MB/CLA 180 COUPE**  
Colour/Trim **021 191 Cosmos Blac/ 041 111 Black**

Account No	Terms	Date/Time Printed	CSE	Operator			
WF001862	Credit	08/04/2022/ 12:28	CH	371 / Go Chee Han			
Description of Goods / Services				Qty	Unit Price	Disc%	Amount

Z REQUEST

Customer Request  
MBPNSUN

POLICY NO/ACC DATE : LIBERTY // 27-3-2022  
DRIVE IN/TP VEH NUMBER : 28-3-2022 // SML2071P - MS FIRST CAPITAL  
DATE IN/DATE SURVEY: 5-4-2022 // RASUL - LKK  
DIRECT SETTLEMENT BY: 1-4-2022 // VIC SANGHILAN - MS FIRST CAPITAL

A BPILAB

DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH.

A BPIRES

RESPRAY REAR BUMPER

A BPILAB

USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD. NETT

A BPILAB

CHECK REAR LIGHTING SYSTEM AND WATER TEST FOR ANY LEAKAGE. NETT

X REAR BUMPER

1.00 1312.82 00.00 1312.82

X REAR LOWER BLACK TRIM, BUMPER

1.00 460.31 00.00 460.31

X REAR BUMPER TRIM STRIP

1.00 150.91 00.00 150.91

Confirmed & accepted by

Nett **4,184.04**  
7% GST on **4184.04** **292.88**

Authorized signatory and company stamp

Total Payable **4,476.92**

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



and Mercedes-Benz are trademarks of Mercedes-Benz Group AG

Pandan Loop Service Center  
188 Pandan Loop  
Singapore 128378  
Tel: 6777 8388  
Fax: 6779 5383  
www.mercedes-benz.com.sg