



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SNE5287P

MS FIRST CAPITAL INSURANCE LIMITED

MOTOR CLAIM DEPARTMENT
6 RAFFLES QUAY
#21-00
SINGAPORE 048580
65073848

Vehicle & Document Information

WIP No 55855
Reg No/Reg Date SNE5287P / 23/03/2022
Date In/Mileage / 0
Chassis No W1K1183842N2865890
Engine No 28291480770390
Make/Model MB/CLA 180 COUPE
Colour/Trim 021 191 Cosmos Blac/ 041 111 Black

Account No	Terms	Date/Time Printed	CSE	Operator
WF001862	Credit	29/03/2022/ 17:43	CH	371 / Go Chee Han

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
---------------------------------	-----	------------	-------	--------

Z REQUEST

Customer Request

M BPNSUN

POLICY NO/ACC DATE : LIBERTY // 27-3-2022

DRIVE IN/TP VEH NUMBER : 28-3-2022 // SML2071P - MS FIRST CAPITAL

DATE IN/DATE SURVEY:

DIRECT SETTLEMENT BY:

A BPILAB

DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH.

A BPIRES

RESPRAY REAR BUMPER

A BPILAB

USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD. NETT

A BPILAB

CHECK REAR LIGHTING SYSTEM AND WATER TEST FOR ANY LEAKAGE. NETT

M REAR BUMPER

1.00 1312.82 00.00 1312.82

M RH/BASIC CARRIER FOR BUMPER

1.00 84.72 00.00 84.72

M REAR LOWER BLACK TRIM, BUMPER

1.00 460.31 00.00 460.31

M REAR BUMPER TRIM STRIP

1.00 150.91 00.00 150.91

M RH/REAR LAMP COMBINATION

1.00 697.17 00.00 697.17

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Confirmed & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378

Nett 5,605.93
7% GST on 5605.93 392.42
Total Payable 5,998.35