



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909		Ref: CS3/CTI22002956/Vty3 Date: 30/03/2022 Code: CTI	
1. Policy Particulars :- (THIRD PARTY CLAIM)			
Insured Veh.	GBH 4850X	Veh. Inspected	SLD 8613R
Policy No.	DMCVSNW00063172102	Coverage (\$)	0.00
Claim No.	SNM22D202121/C02/CHEESC	Excess (\$)	0.00
Assign From	CHEE SO CHOW	Assign Date	30/03/2022
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	27/03/2022	Inspection Date	30/03/2022
Survey held at	2 Kaki Bukit Ave 2, #02-05 Kaki Bukit AutoHub		
Repairer	HL CAR CARE SERVICE CENTRE		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.			