

KS AUTOMOBILE
(Co Reg. No. 53433258K)
60 JALAN LAM HUAT, CARROS CENTRE
#05-68 (S737869)
Tel: 93911482

TO	: CHINA TAIPING	DATE	: 30-Mar-22
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
	Xico Chen.	<u>VEHICLE DETAILS</u>	
	:	VEHICLE NO	: SKR6756M
	:	MODEL	: VOLKSWAGEN POLO
THIRD PARTY REQUESTOR / CONTACT		: DAUD/93911482	WVW 2226RZF 4048467.

QUOTATION SUMMARY

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	TAILGATE ASSY	1	\$ 1,600.66	\$ 1,600.66
2	TAILGATE INNER LOCK	1	\$ 242.00	\$ 242.00
3	TAILGATE EMBLEM TSL	1	\$ 98.00	\$ 98.00
4	TAILGATE EMBLEM 'POLO'	1	\$ 98.00	\$ 98.00
5	TALIGATE EMBLEM 'BLUEMOTION'	1	\$ 98.00	\$ 98.00
6	TAILGATE WEATHERSTRIP	1	\$ 249.00	\$ 249.00
7	REAR BUMPER	1	\$ 1,665.00	\$ 1,665.00
8	REAR BUMPER CENTRE BRACKET	1	\$ 214.00	\$ 214.00
9	REAR BUMPER SIDE RETAINER	2	\$ 120.00	\$ 240.00
10	REAR BUMPER REINFORCEMENT	1	\$ 845.00	\$ 845.00
11	REAR BUMPER UNDER COVER	1	\$ 312.00	\$ 312.00
12	REAR BUMPER REFELCTOR	2	\$ 112.00	\$ 224.00
13	REAR NUMBER PLATE LAMP	2	\$ 85.00	\$ 170.00
14	FRONT PASSENGER AND DRIVER SEAT BELT	2	\$ 898.00	\$ 1,796.00
15	REAR END PANEL	1	\$ 658.00	\$ 658.00
16	REAR END PANEL TOP GARNISH	1	\$ 325.50	\$ 325.50
17	REAR FENDER INNER SHIELD	2	\$ 125.00	\$ 250.00
18	REAR FENDER INNER GARNISH	2	\$ 589.40	\$ 1,178.80
19	EXHAUST MUFFLER	1	\$ 1,445.00	\$ 1,445.00

+
 +
 ✓
 ✓
 ✓
 ✓
 1063
 ✓
 +
 455
 +
 +
 X.
 ✓
 ✓
 ✓
 X
 X
 X

20	EXHAUST HEAT SHIELD <i>3 NP</i>	1	\$ 287.00	\$ 287.00	X
21	EXHAUST MOUNTING RUBBER <i>1 New</i>	2	\$ 28.00	\$ 56.00	X

5054.50
 less 10% : 4549.05

TOTAL PRICE	\$ 12,051.96
LESS 0%	\$ -
SUB TOTAL PRICE	\$ 12,051.96

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	REAR BUMPER CLIPS <i>New</i>	8	\$ 6.50	\$ 52.00	30
2	REAR FENDER COWLING CLIPS <i>3 NP</i>	9	\$ 6.50	\$ 58.50	+
3	END PANEL TOP GARNISH CLIPS <i>1 New</i>	6	\$ 6.50	\$ 39.00	+
4	REAR NUMBER PLATE <i>Deletd</i>	1	\$ 50.00	\$ 50.00	✓
5	TAILLAMP CLIP <i>New</i>	4	\$ 12.00	\$ 48.00	+
6	REAR FENDER INNER TRIM CLIPS <i>New</i>	16	\$ 6.50	\$ 104.00	+
7	REAR END PANEL INSULATION SEAL <i>New</i>	1	\$ 150.00	\$ 150.00	60.
8	REAR FLORR INSULATION SEAL <i>New</i>	1	\$ 180.00	\$ 180.00	+
9	REVERSE SENSOR <i>Dangd</i>	2	\$ 280.00	\$ 560.00	✓
TOTAL				\$1,241.50	700

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

1	TO PANEL BEAT, REMOVE AND REPLACE PARTS	\$ 1,200.00	600	
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,200.00	600	
3	TUFF COAT	\$ 250.00	80	
4	WIRING AND BULB CHECK	\$ 80.00	30	
5	REMOVE AND REFIX CUSHION SEAT/UPHOLSTRY & ROOF LINING TO FACILITATE REPAIR	\$ 250.00	60	
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	50	
7	REMOVE AND REFIX SEAT BELT	\$ 200.00	150	
8	REMOVE AND REFIX REAR WINDSCREEN GLASS	\$ 150.00	X	
9	REMOVE AND REFIX EXHAUST MUFFLER	\$ 180.00	X	

1570

TOTAL

\$3,590.00

ESTIMATE REPORT

TOTAL PARTS COST : \$13,293.46
TOTAL LABOUR COST : \$3,590.00
TOTAL REPAIR COST : \$16,883.46

Adrian Lj

L/S 30/03/22.

05 Days.

total: 6819.05

L/S: 5450

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: