Our Ref

: SNB9906B / TP#1570

Your Ref

: YL135K / CC6/AIG22002959/Kpa3

WITHOUT PREJUDICE

Date : 15TH NOVEMBER 2022

AIG ASIA PACIFIC INSURANCE PTE. LTD.

AIG BUILDING 78 Shenton Way #07-16 Singapore 079120

Attention: Motor Claims Department

ACCIDENT INVOLVING SNB9906B & YL135K ON 28/03/2022 ALONG CTE BEFORE EXIT 15 TOWARDS YIO CHU KANG ROAD

We refer to the above captioned.

We are claiming the below followings:

- Cost of Repair (incl. of GST) S\$ 17,600.77

- Loss of Use S\$ 16.440.00 (\$120.00 x 137 Days)

- LTA / GIA Search Fee S\$ 2.00

Grand Total S\$ 34,042.77

If you have any enquiries, please contact our representative, Mr. Joseph at 6481-1522 or email joseph@ow.sg

All payment is to be issued direct to Optima Werkz Pte Ltd.

Your prompt attention is most grateful and look forward to your speedy settlement.

Yours faithfully

OPTIMA WERKZ PTE LTD Encl.

This is a computer generated printout and no signature is required.

10 Ang Mo Kio Industrial Park 2A #01-05, Singapore 568047 Tel: (+65) 6481 1522 Fax: (+65) 6481 1011 Co Reg & GST No: 201212455W

TAX INVOICE

To: AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120

Tel: 64191000 Fax: 68357416

INV NO. **INVOICE DATE** : 15/11/2022

: 322201398

REF VEH NO.

: TP#1570 : SNB9906B

: TESLA : MODEL 3 MAKE CAR MODEL

CURRENT MILEAGE:

ADVISOR

: NGAI KAR KIT

: COD TERMS

MECHANIC

DESCRIPTION	QTY	UOM	Tax Code	U/P SGD	AM1 SGE
REAR BOOTLID	1	PCS	SR	656.07	656.07
REAR BOOTLID "TESLA" EMBLEM	1	PCS	SR	33.64	33.64
REAR BOOTLID LAMP RH	1	PCS	SR	159.81	159.81
REAR BOOTLID OUTER SWITCH HANDLE	1	PCS	SR	109.35	109.35
REAR BOOTLID MECHANISM LOCK	1	PCS	SR	48.79	48.79
REAR BOOTLID INNER TRIM BOARD	1	PCS	SR	311.21	311.21
REAR BOOTLID HINGE LH	1	PCS	SR	55.51	55.51
REAR BOOTLID HINGE RH	1	PCS	SR	55.51	55.51
REAR BOOTLID STRUT LH	1	PCS	SR	84.11	84.11
REAR BOOTLID STRUT RH	1	PCS	SR	84.11	84.11
REAR TAIL LAMP RH	1	PCS	SR	252.33	252.33
REAR TAIL LAMP BRACKET RH	1	PCS	SR	2.52	2.52
REAR TAIL LAMP REFLECTOR RH	1	PCS	SR	32.81	32.81
REAR BUMPER	1	PCS	SR	597.20	597.20
REAR BUMPER SIDE BRACKET RH	1	PCS	SR	6.73	6.73
REAR BUMPER CENTRE BRACKET	1	PCS	SR	47.11	47.1
REAR BUMPER REFLECTOR RH	1	PCS	SR	18.50	18.50
REAR BUMPER PARKING SENOSR	1	PCS	SR	285.98	285.98
REAR BUMPER PARKING SENSOR BRACKET	1	PCS	SR	8.41	8.4
REAR END PANEL	1	PCS	SR	403.74	403.74
REAR END PANEL TOP GARNISH	1	PCS	SR	269.16	269.16
REAR FENDER RH	1	PCS	SR	1,118.69	1,118.69
REAR FENDER QUARTER GLASS RH	1	PCS	SR	252.33	252.33
REAR FENDER INNER SHIELD RH	1	PCS	SR	105.14	105.14
REAR FENDER INNER PANEL EXTENSION RH	1	PCS	SR	100.94	100.94
REAR FENDER INNER AIR VENT RH	1	PCS	SR	13.46	13.40
REAR WINDSCREEN GLASS	1	PCS	SR	580.37	580.3
REAR WINDSCREEN TOP MOULDING	1	PCS	SR	79.91	79.9
REAR WINDSCREEN BOTTOM MOULDING	1	PCS	SR	58.88	58.8
FRONT BONNET	1	PCS	SR	597.20	597.2
FRONT BONNET HINGE LH	1	PCS	SR	67.29	67.2
FRONT BONNET HINGE RH	1	PCS	SR	67.29	67.2
FRONT BONNET "TESLA" EMBELM	1	PCS	SR	43.74	43.74
FRONT BONNET LOCK	1	PCS	SR	159.81	159.8

10 Ang Mo Kio Industrial Park 2A #01-05, Singapore 568047 Tel: (+65) 6481 1522 Fax: (+65) 6481 1011 Co Reg & GST No: 201212455W

TAX INVOICE

To: AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120

Tel: 64191000 Fax: 68357416 INV NO. **INVOICE DATE** : 15/11/2022

: 322201398 : TP#1570

REF VEH NO. MAKE

: SNB9906B

: TESLA : MODEL 3 CAR MODEL

CURRENT MILEAGE:

ADVISOR : NGAI KAR KIT

: COD TERMS MECHANIC

DESCRIPTION	QTY	UOM	Tax Code	U/P SGD	AMT SGD
FRONT BONNET STRIKER	1	PCS	SR	2.52	2.52
FRONT LUGGAGE COMPARTMENT	1	PCS	SR	58.04	58.04
FRONT LUGGAGE COMPARTMENT MAT	1	PCS	SR	67.29	67.29
FRONT HEADLAMP RH	1	PCS	SR	1,177.57	1,177.09
FRONT BUMPER	1	PCS	SR	597.20	597.20
FRONT BUMPER SIDE BRACKET RH	1	PCS	SR	8.42	8.42
FRONT BUMPER CENTRE UPPER BRACKET RH	1	PCS	SR	10.94	10.94
FRONT BUMPER LOWER GRILLE	1	PCS	SR	92.52	92.52
FRONT BUMPER REINFORCEMENT	1	PCS	SR	243.93	243.93
FRONT BUMPER ABSORBER FOAM	1	PCS	SR	42.06	42.06
FRONT BUMPER REINFORCEMENT CRUSH CAN RH	1	PCS	SR	47.11	47.11
FRONT SUPPORT BEAM	1	PCS	SR	664.49	664.49
FRONT SUPPORT BEAM BRACKET RH	1	PCS	SR	6.73	6.73
FRONT BUMPER PARKING SENSOR	1	PCS	SR	285.98	285.98
FRONT BUMPER PARKING SENSOR BRACKET	1	PCS	SR	8.41	8.41
FRONT RADAR SENSOR	1	PCS	SR	311.21	311.21
FRONT RADAR SENSOR SUPPORT BRACKET	1	PCS	SR	6.73	6.73
FRONT FENDER RH	1	PCS	SR	403.74	403.74
REAR BOOTLID RUBBER GUIDE STOPPER RH	1	PCS	SR	1.68	1.68
REAR BOOTLID WEATHERSTRIP	1	PCS	SR	109.35	109.35
FRONT FENDER INNER BRACKET RH	1	PCS	SR	21.02	21.02
FRONT BUMPER SIDE LAMP RH	1	PCS	SR	243.93	243.93
REAR BOOTLID LAMP LH	1	PCS	SR	159.81	159.81
REAR BUMPER WIRE HARNESS	1	PCS	SR	361.68	361.68
REAR TAILLAMP STOPPER RH	1	PCS	SR	10.94	10.94
A/C COMPRESSOR BRACKET	1	PCS	SR	26.92	26.92
FRONT NUMBER PLATE GARNISH	1	PCS	SR	26.92	26.92
REAR BOOTLID INNER TRIM CLIPS	1	PCS	SR	50.00	50.00
REAR BUMPER CLIPS	1	PCS	SR	60.00	60.00
REAR END PANEL JOINT SEALANT	1	PCS	SR	30.00	30.00
REAR FENDER QUARTER GLASS SEALANT RH	1	PCS	SR	30.00	30.00
REAR FENDER INNER SHIELD CLIPS	1	PCS	SR	40.00	40.00
REAR WINDSCREEN GLASS SEALANT	1	PCS	SR	40.00	40.00
REAR NUMBER PLATE & HOLDER	1	PCS	SR	45.00	45.00

10 Ang Mo Kio Industrial Park 2A #01-05, Singapore 568047 Tel: (+65) 6481 1522 Fax: (+65) 6481 1011 Co Reg & GST No: 201212455W

TAX INVOICE

To: AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#08-16 AIG BUILDING

SINGAPORE 079120

Tel: 64191000

Fax: 68357416

INV NO. **INVOICE DATE** : 15/11/2022

: 322201398

REF

VEH NO.

: TP#1570 : SNB9906B

MAKE : TESLA CAR MODEL 3 : MODEL 3

CURRENT MILEAGE:

ADVISOR : NGAI KAR KIT

TERMS : COD MECHANIC :

DESCRIPTION	QTY	UOM	Tax Code	U/P SGD	AMT SGD
FRONT BUMPER CLIPS	1	PCS	SR	60.00	60.00
LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST ACCIDENT AREAS & ETC.	1	JOB	SR	1,700.00	1,700.00
LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT ACCIDENT AREAS & ETC.	1	JOB	SR	1,960.00	1,960.00
LABOUR CHARGES TO REMOVE & REPLACE FRONT & REAR PARKING SENSOR.	1	JOB	SR	120.00	120.00
LABOUR CHARGES TO REMOVE & REFIX REAR FENDER INNER TRIM & UNHOLDSTERY CUSHION SET & ETC. TO EFFECT REPLACE OF REAR FENDER RH.	1	JOB	SR	120.00	120.00
LABOUR CHARGES TO REMOVE & REPLACE REAR WINDSCREET	1	JOB	SR	120.00	120.00
LANBOUR CHARGES TO REMOVE & REFIX REAR QUARTER GLASS LH & ETC.	1	JOB	SR	60.00	60.00
TO DIAGNOSE FAULT CODE & RESET MEMORY.	1	JOB	SR	150.00	150.00
TO CHECK WIRING & ELECTRICAL SYSTEM & ETC.	1	JOB	SR	40.00	40.00
TO TUFF KOTE & UNDERSEAL MATERIALS.	1	JOB	SR	60.00	60.00

10 Ang Mo Kio Industrial Park 2A #01-05, Singapore 568047 Tel: (+65) 6481 1522 Fax: (+65) 6481 1011 Co Reg & GST No: 201212455W

TAX INVOICE

To: AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120

Tel: 64191000 Fax: 68357416 INV NO.

: 322201398

INVOICE DATE

: 15/11/2022 : TP#1570

REF VEH NO.

: SNB9906B

MAKE

: TESLA

CAR MODEL

: MODEL 3

CURRENT MILEAGE:

ADVISOR

: NGAI KAR KIT

TERMS MECHANIC : COD

DESCRIPTION

QTY **UOM**

Tax Code

U/P SGD AMT SGD

Remarks: DOA: 28/03/2022 @ 13:45HRS

CLAIMANT: KWAN MING FENG, KELWIN

TP VEHICLE: YL135K

Singapore Dollars: Seventeen Thousand Six Hundred And Cent Seventy-Seven Only

SUB TOTAL SGD

TOTAL

16,449.31

GST 7.00% SGD

SGD

1,151.46 17,600.77

OUTSTANDING

SGD

17,600.77

Tax SR

Amount

Tax Legend:

16,449.31

I/We confirm that I/We incurred the repair costs herein and will observe my/our agreement with the repairs. I/We declare the repairs for above vehicle have been completed to my/our satisfaction.

SR - Standard Rated ZR - Zero Rated OS - Out of Scope

- 1) New parts purchased and installed by Optima Werkz Pte Ltd, will be entitled to warranty period of one (1) year or mileage up to 30,000km, whichever comes first, from the date of invoice, with the exception to wear & tear items.
- 2) Recon Parts purchased and installed by Optima Werkz Pte Ltd, will be entitled to warranty period of six (6) months or mileage up to 10,000km, whichever comes first, from the date of invoice, with the exception to wear
- 3) Goods sold are not refundable/returnable.
- 4) Original Invoice is only valid when the payment is acknowledge receipt by Optima Werkz Pte Ltd. Interest of 2% per month will be charged on any outstanding amount

Customer Acknowledgement

Opt for a more convenient and quicker way to pay via Bank Transfer or PayNow: Beneficiary Name: Optima Werkz Pte Ltd Beneficiary Bank Name: DBS Bank Ltd

Bank Account No.:0039441282 Swift Code: DBSSSGSG

PayNow UEN: 201212455WDB1

Note: Please include your invoice number under the reference section

For Optima Werkz Pte Ltd

Authorised Signature

Customer Name and Signature

INSURER ENQUIRY

Find insurer

Vehicle reg. no.

YL135K

Date of Accident

28/03/2022



Reset

% RESULT & RECEIPT

TP Insurer Enquiry

Insurance AIG Asia Pacific Insurance Pte.... Requested Date _______28/03/2022 15:54

Payment details

Request Amount: \$\$1.87 GST Amount: \$\$0.13

Total Amount Due (GST Inclusive): \$\$2

General Insurance Association

Records Management Centre GST Registration No: M400017735

AUTHORISATION TO ACT

I/We, Kwan Ming Feng, Kelvin ("the third party claimant") of SNB 9906B Blk 327 River Valley Rd #22-03 (address), owner of SNB 9906B (vehicle no.) hereby authorize Opting Works Ate Ud ("the workshop")	
no.) hereby authorize Optima Wertz Pte Ud ("the workshop")	
to act for me with respect to my claim for repair costs and/or rental and/or loss of use	
("claim") for my vehicle no. That was damaged pursuant to the accident which	
to act for me with respect to my claim for repair costs and/or rental and/or loss of use ("claim") for my vehicle no. SMB 9906 B was damaged pursuant to the accident which occurred on Show claim along CTE Before CHA to towards the Chartes (location) involving vehicle no/s YL 1356 ("the accident").	ngRe
(location) involving vehicle no/s ————————————————————————————————————	
I further authorize the workshop to settle my above mentioned claim in a manner that they deem fit and the workshop is further authorized to receive payment further to settlement of my claim with payment cheque/s being made in favour of the workshop.	
I further acknowledge that any settlement the workshop may reach on my behalf is on a	
without prejudice and without admission of liability basis insofar as the driver/owner/insurers	
of the other vehicle/s is concerned.	

Signed by "the workshop"

(with chop) ARY CHUA

Dated this ______ (day) of March _____ (month) 2022 (year)

Signed by "the third party claimant"

(with chop if applicable)