

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/EGI22002961/KTY3N2**Date:** 28/04/2022REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd. Policy No:
Claimant Vehicle No : SJJ2333E **Insured Vehicle No :** SLL8963M
 Date of Loss: 28/03/2022 Nature of Claim: TP Claim No: CDMPG22000553

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJJ2333E**
 Make & Model: AUDI Q3 SPORTBACK, 1.4 TFSI S TRONIC (17) (A) Engine No: CZDC06742
 Reg. Date: 30/09/2020 (Man. Year: 2020) Chassis No: WAUZZZF32M1013834
 Colour: Metallic Blue Odometer: 18547 km
 Engine Capacity: 1395 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/55R18 Rear Tyre Size: 235/55R18
 Front Left Side: Pirelli 8 mm Rear Left Side: Pirelli 8 mm
 Front Right Side: Pirelli 8 mm Rear Right Side: Pirelli 8 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|--|-------------------|-------------------|-------------------|---------------|
| Parts | 10,243.10 | 5,098.14 | 5,144.96 | 50.23 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 3,850.00 | 1,140.00 | 2,710.00 | 70.39 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 14,093.10 | 6,238.14 | 7,854.96 | 55.74 |
| Approved Total (Overridden) (S\$) | | 5,000.00 | | |
| (S\$) | 14,093.10 | 5,000.00 | 9,093.10 | 64.52 |
| + GST 7.00/7.00% (S\$) | 986.52 | 350.00 | 636.52 | 64.52 |
| Nett Amount (S\$) | 15,079.62 | 5,350.00 | 9,729.62 | 64.52 |

INSPECTION

Date of Assignment: 30/03/2022
 Date Inspected: 31/03/2022 Inspected At: Optima Werkz Pte Ltd (HQ)
 10 Ang Mo Kio Industrial Park 2A, #01-05 AMK
 Autopoint
 Singapore 568047
 Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 27 Apr 2022)**Parts:** M1-SUV AUDI Q3 SPORTBACK 1.4 TFSI S TRONIC (17) (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** (Unsubmitted, no print-code for SJJ2333E)**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Recommended Parts**

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|----------------------------------|---------------|-------------|--------------|
| 1 | 1 | | *FRONT BUMPER LH | Mtg Cracked | 1,283.00 FL | *1,068.00 FL |
| 2 | 1 | | *FRONT GRILLE WITH CHROME | Cracked | 1,777.00 FL | *1,636.00 FL |
| 3 | 1 | | *FRONT GRILLE LOWER GARNISH | Serviceable | 366.00 FL | *- FL |
| 4 | 2 | | *FRONT PARKING SENSORS | Serviceable | 550.00 FL | *- FL |
| 5 | 1 | | *FRONT SPONGE | Cracked | 126.00 FL | *126.00 FL |
| 6 | 1 | | *FRONT REINFORCEMENT | Repair | 838.00 FL | *- FL |
| 7 | 1 | | *REAR BUMPER | Mtg Cracked | 1,544.00 FL | *1,307.20 FL |
| 8 | 1 | | *END PANEL INNER | Repair | 723.00 FL | *- FL |
| 9 | 1 | | *END PANEL OUTER | Repair | 422.00 FL | *- FL |
| 10 | 1 | | *END PANEL TOP COVER | Serviceable | 394.00 FL | *- FL |
| 11 | 1 | | *REAR REFLECTOR LH | Serviceable | 85.00 FL | *- FL |
| 12 | 1 | | *REAR REFLECTOR RH | Serviceable | 85.00 FL | *- FL |
| 13 | 1 | | *REAR REFLECTOR COVER LH | Serviceable | 179.00 FL | *- FL |
| 14 | 1 | | *REAR REFLECTOR COVER RH | Serviceable | 179.00 FL | *- FL |
| 15 | 4 | | *REAR PARKING SENSORS | Serviceable | 1,100.00 FL | *- FL |
| 16 | 1 | | *FRONT BUMPER CLIPS | Necessary | 100.00 FS | *100.00 FS |
| 17 | 1 | | *FRONT GRILLE CLIPS | Necessary | 80.00 FS | *80.00 FS |
| 18 | 1 | | *FRONT LICENSE PLATE WITH HOLDER | Dented | 75.00 FS | *25.00 FS |
| 19 | 1 | | *REAR BUMPER CLIPS | Necessary | 100.00 FS | *100.00 FS |
| 20 | 1 | | *REAR LOWER BUMPER CLIPS | Necessary | 100.00 FS | *100.00 FS |
| 21 | 1 | | *END PANEL COVER CLIPS | Not Necessary | 60.00 FS | *- FS |
| 22 | 1 | | *REAR LOWER BUMPER | Buckled | 464.00 FL | *459.00 FL |
| 23 | 1 | | *REAR REINFORCEMENT | Bent | 596.00 FL | *520.40 FL |
| 24 | 1 | | *REAR SPONGE | Cracked | 98.00 FL | *98.00 FL |

F=Franchise part. S=SpcNett. L=ListItemDisc.

| | | |
|--|------------------|-----------------|
| Sub Total (\$\$) | 11,324.00 | 5,619.60 |
| - List Item Discount on L Items 10.00/10.00% (\$\$) | 1,080.90 | 521.46 |
| Total Parts (\$\$) | 10,243.10 | 5,098.14 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|---------------------|--|----------|---------------------------------|-----------------|
| Labour Items | | | | |
| 1 | LABOUR CHARGES TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT ACCIDENT AREA | New | 800.00 | 200.00 |
| 2 | LABOUR CHARGES TO REMOVE,REFIX,REPAIR & READJUST REAR ACCIDENT AREA | New | 800.00 | 300.00 |
| 3 | LABOUR CHARGES TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR ACCIDENT AREA | New | 1,000.00 | 400.00 |
| 4 | TO TUFF KOTE & UNDERSEAL MATERIALS | New | 200.00 | 0.00 |
| 5 | TO CHECK WIIRNG & ELECTRICAL SYSTEM & ETC | New | 180.00 | 40.00 |
| 6 | TO DIAGNOSE & RESET FAULT CODE | New | 170.00 | 0.00 |
| 7 | LABOUR CHARGES TO REMOVE,REFIX,REPAIR & READJUST FRONT ACCIDENT AREA | New | 700.00 | 200.00 |
| | | | Gross Labour Cost (\$\$) | 3,850.00 |
| | | | | 1,140.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >