

OPTIMA WERKZ

OPTIMA WERKZ PTE LTD
Co. Reg. No. 20121455W
www.ow.sg

SINGAPORE

f /OptimaWerkz

o /OptimaWerkz

Date: 29.03.2022
Vehicle No: SLL8963M
Model: AUDI Q3 SPORTBACK 1.4 TFSI
Chassis: WAUZZF32M1013834
Reg. Year: 2019-2020

555 2333E
Not Not hatched
Permy B4 paint
4 days
118mp @ 5000h

Third Party Insurer: ERGO LONPAC SLL8963M
Third Party Veh No: GBD4484R
Date of Accident: 05-10-2021-28/03/22
Estimate: VICTOR
Surveyor:

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	FRONT BUMPER LH 1068	1	mt	\$1,283.00
2	FRONT GRILLE WITH CHROME 1636	1	cm	\$1,777.00
3	FRONT GRILLE LOWER GARNISH	1	sm	\$366.00
4	FRONT PARKING SENSORS	2	\$275.00	\$550.00
5	FRONT SPONGE	1	cm	\$126.00
6	FRONT REINFORCEMENT	1	r	\$838.00
7	REAR BUMPER 1307.20	1	mt	\$1,544.00
8	REAR LOWER BUMPER 459	1	ru	\$464.00
9	REAR REINFORCEMENT 520.40	1	ru	\$596.00
10	REAR SPONGE	1	cm	\$98.00
11	END PANEL INNER	1	r	\$723.00
12	END PANEL OUTER	1	r	\$422.00
13	END PANEL TOP COVER	1	ru	\$394.00
14	REAR REFLECTOR LH	1	ru	\$85.00
15	REAR REFLECTOR RH	1	ru	\$85.00
16	REAR REFLECTOR COVER LH	1	ru	\$179.00
17	REAR REFLECTOR COVER RH	1	ru	\$179.00
18	REAR PARKING SENSORS	4	\$275.00	\$1,100.00
SUB TOTAL				\$10,809.00
LESS 10%				-\$1,080.90
PARTS TOTAL				\$9,728.10

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	FRONT BUMPER CLIPS	1	ru	\$100.00
2	FRONT GRILLE CLIPS	1	ru	\$80.00
3	FRONT LICENSE PLATE WITH HOLDER	1	ru	\$75.00
4	REAR BUMPER CLIPS	1	ru	\$100.00
5	REAR LOWER BUMPER CLIPS	1	ru	\$100.00
6	END PANEL COVER CLIPS	1	ru	\$60.00
S/N TOTAL				\$515.00

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REFIX, REPAIR & READJUST FRONT ACCIDENT AREA.

2001
\$700.00

Head office

8 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9010 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



128.90
1,729.00
1,729.00
1,729.00

OPTIMA WERKZ

SINGAPORE

OPTIMA WERKZ PTE LTD
Co. Reg. No. 201212455W

www.ow.sg

f /OptimaWerkz

● /OptimaWerkz

Date: 29.03.2022
Vehicle No: SLL8963M
Model: AUDI Q3 SPORTBACK 1.4 TFSI
Chassis: WAUZZZF32M1013834
Reg. Year: 2019

Third Party Insurer: LONPAC
Third Party Veh No: GBD4484R
Date of Accident: 05.10.2021
Estimate: VICTOR
Surveyor:

LABOUR CHARGES TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT ACCIDENT ARE.	\$800.00	2001
LABOUR CHARGES TO REMOVE, REFIX, REPAIR & READJUST REAR ACCIDENT AREA.	\$800.00	3001
LABOUR CHARGES TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR ACCIDENT AREA.	\$1,000.00	4001
TO TUFF KOTE & UNDERSEAL MATERIALS.	\$200.00	in X
TO CHECK WIRING & ELECTRICAL SYSTEM & ETC.	\$180.00	401
TO DIAGNOSE & RESET FAULT CODE.	\$170.00	in X
	<u>LABOUR TOTAL</u>	<u>\$3,850.00</u>
	TOTAL	\$14,093.10

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Head office
6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch
9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)
Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011

