



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO22002966/Kqy3e2	
			Date: 21/12/2022	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBA 7205B		Veh. Inspected	SLF 3246P
Policy No.			Coverage (\$)	0.00
Claim No.	CMTD2200989/LOR		Excess (\$)	0.00
Assign From	MELVIN YE		Assign Date	30/03/2022
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA AXIO (A)		c.c	1496
Engine No.	HIDDEN		Year of Reg.	2016
Chassis No.	NRE1610016103		Colour	WHITE
Odometer	155146 KM		Steering	IN ORDER
Brakes	IN ORDER		Modification	NIL
General	GOOD			
3. Conditions of Tyres				
		Size	Make	Balance
R/H Front Tyre		185/60 R15	WEST LAKE	3 mm
L/H Front Tyre		185/60 R15	WEST LAKE	3 mm
R/H Rear Tyre		185/60 R15	WEST LAKE	8 mm
L/H Rear Tyre		185/60 R15	WEST LAKE	8 mm
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	23/03/2022		Inspection Date	06/04/2022
Survey held at	MOHAMED ELECTRO-MART 38 WOODLANDS INDUSTRIAL PARK E1 #01-16 SINGAPORE 757700			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			3 Working Days	