

Vehicle Number : **GBL5675H**  
 Vehicle Model : **TOYOTA HIACE**  
 Accident Date : **28.03.2022**  
 Original Reg Date : **27.10.2021**

Date : **29.03.2022**  
 Chassis : **GDH2012018684**  
 TP Ins. : **AIG**

*TP Alh.  
Xiao Tony*

**ESTIMATE**

1	1 pc	TAILGATE <i>Dented.</i>			<u>2,045.30</u>	X
2	1 pc	TAILGATE INNER BOARD <i>Ne m</i>			298.60	X
3	1 pc	TAILGATE OUTER GARNISH <i>Ne m</i>			365.80	X
4	1 pc	TAILGATE LOGO <i>Ne w</i>			98.70	/
5	1 pc	TAILGATE HIACE STICKER <i>Ne w</i>			<del>86.30</del>	45
6	1 pc	TAILGATE 1200KG STICKER <i>Ne w</i>			<del>85.60</del>	48.
7	1 pc	TAILGATE INNERLOCK <i>Damaged.</i>			<u>485.30</u>	358.
8	1 pc	TAILGATE WEATHERSTRIP <i>Ne w</i>			225.60	/
9	1 pc	TAILGATE WINDSCREEN INNER SEAL <i>Ne w</i>			60.00	/
10	1 pc	TAILGATE WINDSCREEN MOLDING <i>Ne w</i>			185.60	/
11	2 pc	TAILAMPS <i>LH cracked.</i>	385.60		771.20	385.60
12	2 pc	REAR CORNER BUMPER <i>LH Dented</i>	198.60		<del>397.20</del>	198.60.
13	2 pc	REAR CORNER BUMPER RETAINERS <i>Ne m</i>	98.60		197.20	X.
14	1 pc	REAR BUMPER <i>Dented.</i>			485.60	/
15	2 pc	Rear bumper retainers <i>Ne w LH mtd</i>	98.60		<del>197.20</del>	65
16	2 pc	REAR FENDER AIRDUCT <i>Ne m</i>	75.60		151.20	X.
17	1 PC	END PANEL OUTER <i>Dented.</i>			468.30	/
18	1 pc	END PANEL INNER <i>Reps</i>			498.60	X.
19	1 pc	END PANEL TOP PLATE <i>Ne w</i>			356.90	X
20	1 pc	FLOOR PANEL VINYL MAT <i>Ne w Ne w</i>			398.60	X.
				subtotal	7,858.80	

*4669.30  
3501.97*

**Special Nett**

1	1 pc	Rear number plate with casing <i>Not Nec</i>			50.00	X
2	1 set	Rear bumper clips <i>Ne w</i>			30.00	/
3	1 set	TAILGATE inner board clips <i>Not Nec</i>			30.00	X.
4	2 set	Tailamps clips <i>Ne w</i>	30.00		<del>60.00</del>	30
5	1 set	Rear Windscreen sealant <i>Ne w</i>			80.00	60.
6	1 set	Rear bumper reverse sensors <i>Dand</i>			250.00	200.
7	1 set	end panel sealant <i>Ne w</i>			60.00	/

*380*

**Labour charge**

Panel Beating	1,800.00	<i>800.</i>
Spray painting	<del>1,800.00</del>	<i>800.</i>
Check Wiring on tailamp	120.00	<i>30</i>
Anti rust	<del>100.00</del>	<i>80.</i>

Remove and install reverse sensor		120.00	50
Remove and install rear tailgate and mechanism		150.00	80
Remove and install rear tailgate windscreen		150.00	120
Remove and install interior upholstery		150.00	40

2000

total 12,808.80

total: 5881.97

L/s: A.7K

06 Days.

**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: