

CC3/AIG 22002970/GVC

 PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE	:	ACCIDENT REPAIRS
WORKSHOP	:	UBI ROAD 1
CONTACT NO	:	6366 2323
FAX NO	:	6841 1183
REFERENCE	:	PA/OD/0243/2022/JT
DATE	:	29-Mar-22
WIP	:	17683

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 29/3/22

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME	:	MS HEENA KARAMCHANDANI MAYANI
ADDRESS	:	1 JALAN KUALA THE MORNINGSIDE CONDO SINGAPORE 239639
TELEPHONE	:	HP +65 92966433
TYPE OF CLAIM	:	OWN DAMAGE CLAIM
POLICY NO	:	1800139423-03
VEHICLE NO	:	SMF 7309 D
MODEL CODE	:	AUDI Q5 2.0 TFSI S QU
MODEL YEAR	:	22/11/2018
ENGINE NO	:	DAX 046353
CHASSIS NO	:	WAUZZZF8J2238194
MILEAGE	:	-
DATE IN	:	-
ESTIMATED BY	:	JOHNNY BOO / ALLAN WU
ACCIDENT DATE	:	15-Mar-22
PLACE OF ACCIDENT	:	CHURCH ST TOWARDS COLLYER QUAY

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMF 7309 D

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS ,OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00	X N/A
2	TO REMOVE AND TRANSFER, LHS FORNT DOOR AND LHS REAR DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$ 800.00	/ ✓
3	TO DISMANTLE AND REINSTALL FRONT BUMPER. TO RENEW LHS FRONT FENDER, LHS FRONT DOOR AND LHS REAR DOOR. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 4,000.00	2000 1000 ✓
4	TO RESPRAY LHS FRONT FENDER, LHS FRONT DOOR, LHS REAR DOOR, 2 DOOR COVERS, BOTH FRONT WHEEL ARCH TRIMS AND LHS REAR WHEEL ARCH TRIM.	\$ 5,000.00	2550 1600 ✓
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	/ ✓
TOTAL LABOUR CHARGES		: \$ 10,472.00	

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMF 7309 D - FRONT

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT FENDER - LH Back X NC	1	\$ 1,462.00		
2	FRONT FENDER BRACKET - LH X	1	\$ 20.00		
3	FRONT FENDER BRACE - LH X	1	\$ 250.00		
4	FRONT WHEEL HOUSING LINER X	1	\$ 303.00		
5	"S-LINE" EMBLEM X NC	1	\$ 133.00		
6	FRONT WHEEL ARCH COVER - LH / RH X NC	2	\$ 1,418.00		
7	FRONT DOOR - LH Back X	1	\$ 4,390.00	3512	
8	FRONT DOOR BUNGS - LH X	1	\$ 5.00		
9	FRONT DOOR OUTER SEAL - LH Back X	1	\$ 229.00	182.80	
10	BONDING AGENT ? X	1	\$ 51.00		
11	CLEANING SOLUTION ? X	1	\$ 74.00		
12	APPLICATOR ? X	1	\$ 8.00		
13	GROMMET ? X	5	\$ 16.00		
14	FRONT DOOR ATTACHMENT PARTS X	1	\$ 276.00		
15	FRONT DOOR CATCH - LH ? X	1	\$ 163.00		
16	FRONT DOOR COVER - LH Cut X	1	\$ 833.00	666.40	
SUB TOTAL SPARE PARTS		:	\$ 9,631.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMF 7309 D - REAR

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
1	REAR DOOR - LH <i>180</i>	1	\$	4,390.00	<i>3512.00</i>
2	REAR DOOR OUTER SEAL - LH <i>180</i>	1	\$	229.00	<i>182.80</i>
3	BONDING AGENT <i>? X</i>	1	\$	51.00	
4	CLEANING SOLUTION <i>? X</i>	1	\$	74.00	
5	APPLICATOR <i>? X</i>	1	\$	8.00	
6	REAR DOOR SEALING STRIP <i>180</i>	1	\$	19.00	<i>1464</i>
7	GROMMET <i>? X</i>	1	\$	10.00	
8	REAR DOOR SEAL OUTER - LH <i>X NN</i>	1	\$	247.00	
9	REAR DOOR CATCH - LH <i>X NN</i>	1	\$	163.00	<i>116.40</i>
10	REAR SILL PANELL SEAL - LH <i>X NN</i>	1	\$	282.00	
11	REAR DOOR COVER - LH <i>180</i>	1	\$	728.00	<i>582.40</i>
12	REAR WHEEL COVER - LH <i>X NN</i>	1	\$	615.00	
13	SUNDRIES <i>? X</i>		\$	350.00	<i>22.16</i>
TOTAL SPARE PARTS		:	\$	16,797.00	
TOTAL LABOUR CHARGES		:	\$	10,472.00	
GRAND TOTAL		:	\$	27,269.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

MIUM AUTOMOBILES



1, ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

Guo Qian
20/3/22

before part photos.

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORA KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

5 & Days.

Not Authorised.

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) allowed
- Supplemental items must be approved and is subject to approval by the Company

Acknowledged: _____
Signature: _____
Date: _____