

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

Name : LIANG LONG MARINE PTE LTD

Make/Model : HONDA VEZEL

Vehicle No : SLP96755

Accident date : 28.03.2022

TP China. Xigo Tong.

No	DESCRIPTION	Qty	Amount (\$\$)
List Items			
1	Rear windscreen rubber <i>Nec</i>	1	\$ 168.30 ✓
2	Rear tailgate <i>Distorted</i>	1	\$ 1,360.00 ✓ 1100
3	Rear tailgate hinges @ \$60.50 <i>Not new</i>	2	\$ 121.00 X
4	Rear tailgate upper lock <i>Jammed</i>	1	\$ 221.10 ✓
5	Rear tailgate lower lock <i>HM</i>	1	\$ 71.50 X
6	Rear tailgate shock absorber @ \$198.00 <i>Damaged</i>	2	\$ 396.00 ✓
7	Rear tailgate inner board <i>Cracked</i>	1	\$ 231.00 ✓
8	Rear tailgate reflector @ \$413.20 <i>LH smashed, RH not</i>	2	\$ 826.40 ✓
9	Rear tailgate "H" emblem	1	\$ 38.50 ✓
10	Rear tailgate "Vezel" emblem	1	\$ 38.50 ✓
11	Rear tailgate inner handle <i>Not new</i>	1	\$ 25.30 X
12	Rear tailgate top garnish <i>Cracked</i>	1	\$ 325.10 ✓
13	Rear tailgate weather strip <i>LT</i>	1	\$ 106.70 ✓
14	Rear tailgate top spoiler <i>Cracked</i>	1	\$ 728.90 ✓
15	Rear tailgate inner top centre garnish <i>Not new</i>	1	\$ 92.00 X
16	Rear tailgate inner side garnish @ \$58.30 <i>LH Del'd</i>	2	\$ 116.60 ✓ 58.30
17	Rear number plate lamp @ \$71.50 <i>Not new</i>	2	\$ 143.00 X
18	Rear end panel <i>Distorted</i>	1	\$ 585.10 ✓
19	Rear end panel inner top garnish <i>Del'd</i>	1	\$ 82.50 ✓
20	Rear end panel outer buzzer assy smart <i>Damaged</i>	1	\$ 198.00 ✓
21	Rear lamp @ \$461.00 <i>LH smashed, RH cracked</i>	2	\$ 922.00 ✓
22	Rear lamp lower garnish @ \$198.00 <i>LH distorted, RH torn</i>	2	\$ 396.00 ✓
23	Rear bumper <i>Distorted</i>	1	\$ 858.00 ✓ 745
24	Rear bumper side holder @ \$30.80 <i>Damaged</i>	2	\$ 61.60 ✓
25	Rear bumper reflector @ \$141.10 <i>LH Smashed</i>	2	\$ 282.20 ✓ 141.10
26	Rear bumper lower chrome <i>Not new</i>	1	\$ 170.50 X
27	Rear fender <i>Distorted</i>	1	\$ 884.70 ✓
28	Rear inner fender <i>Distorted</i>	1	\$ 685 ✓
29	Rear fender inner shield @ \$231.00 <i>LH torn</i>	2	\$ 462.00 ✓ 231
30	Rear fender inner side garnish @ \$418.00 <i>LH Cracked, RH Del'd</i>	2	\$ 836.00 ✓ 660
31	Rear fender side garnish @ \$341.00 <i>LH Missing</i>	2	\$ 682.00 ✓ 185
32	Rear spare tyre top board <i>Del'd</i>	1	\$ 319.00 ✓
33	Rear spare tyre well <i>Cracked</i>	1	\$ 1130 ✓
34	Rear spare tyre lower cover <i>Torn</i>	1	\$ 264.00 ✓

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

Name : LIANG LONG MARINE PTE LTD
Vehicle No : SLP9675S

Make/Model : HONDA VEZEL
Accident date : 28.03.2022

No	DESCRIPTION	Qty	Amount (\$\$)
35	Rear spare top sponge <i>Cracked</i>	1	\$ 285.40
36	Rear spare tyre well insulation @ \$101.20 <i>He new</i>	3	\$ 303.60
37	Rear LH lamp panel <i>Distorted</i>	1	\$ 162.80
38	Rear LH lamp top panel <i>2 Distorted</i>	1	\$ 94.20
39	Rear LH lamp lower panel	1	\$ 55.00
40	Rear LH door <i>Dented</i>	1	\$ 980.70
41	Rear LH door inner board <i>He new</i>	1	\$ 762.90
42	Rear LH door inner lock <i>Dented</i>	1	\$ 546.20
43	Rear LH door handle <i>He new</i>	1	\$ 180.60
44	Rear LH door frame sticker <i>He new</i>	1	\$ 195.80
45	Rear LH door weather strip <i>He new</i>	1	\$ 190.80
46	Rear LH shock absorber <i>He new</i>	1	\$ 330.60
47	Rear LH wheel hub bearing assy <i>Damaged</i>	1	\$ 455.80
48	Rear LH axle beam <i>He new</i>	1	\$ 1,513.20
49	Rear floor board handle @ \$75.00 <i>He new</i>	2	\$ 150.00
50	Upholstery assy <i>Stained</i>	1	\$ 1,184.00
51	Petrol tank pipe <i>Best</i>	1	\$ 297.00
52	LH roof top side panel <i>1415</i>	1	\$ 420.70
53	Rear wiper motor <i>Damaged</i>	1	\$ 475.00
			\$ 22,422.60
			\$ 4,484.52
			\$ 17,938.08

15916.70 S.N: 60
12733.36
Less 20% Disc
Total

Special Nett Items

1	Rear bumper reverse sensor (1 set) <i>Damaged</i>	1	\$ 380.00
2	Rear camera <i>Dented</i>	1	\$ 800.00
3	Rear bumper clips (1 set) <i>He new</i>	1	\$ 70.00
4	Rear number plate <i>2 Distorted</i>	1	\$ 50.00
5	Rear number plate holder	1	\$ 50.00
6	Rear LH sport rim <i>He new</i>	1	\$ 680.00
7	Rear LH tyre <i>He new</i>	1	\$ 380.00
			\$ 2,410.00

850

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

Name : LIANG LONG MARINE PTE LTD
Vehicle No : SLP96755

Make/Model : HONDA VEZEL
Accident date : 28.03.2022

No	DESCRIPTION	Qty	Amount (\$\$)
----	-------------	-----	---------------

Labour Cost

1	Towing fee		\$ 130.00	60
2	To check wiring		\$ 60.00	30
3	To supply rear end panel inner sealant		\$ 200.00	60
4	To supply rear windscreen sealant		\$ 50.00	✓
5	To reset		\$ 100.00	X
6	To check wheel alignment		\$ 100.00	80.
7	Remove & reinstall rear windscreen		\$ 200.00	120
8	Remove & reinstall reverse sensor		\$ 200.00	50
9	Remove & reinstall exhaust pipe		\$ 200.00	X
10	Remove & reinstall camera		\$ 100.00	50
11	Remove & reinstall bootlid inner garnish		\$ 200.00	80.
12	Remove & reinstall petrol tank		\$ 200.00	80
13	Remove & refix cushion and upholstery rear seat		\$ 300.00	250.
14	Remove & refix door fittings		\$ 100.00	80.
15	Remove ,replace & repair consistent to the accident		\$ 3,500.00	2000
16	Respray painting		\$ 2,800.00	1500.
17	Tuff kote		\$ 150.00	100.
Total			\$ 8,590.00	

4590

Grand Total \$ 28,938.08

Supplementary: 2107.68

total: 20341.04

1/8: 16.2K.

17 Days.

16.2K

17 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

SLP 9675S

Supplementary.

Tailgate Glass Shattered 1266.80 ✓
Tailgate Glass Solar Film. ^{new} ~~280(SN)~~ 120(SN)
Upholstery Assy Clips. ^{new} ~~100(SN)~~ 60(SN)
Tailgate Antenna Sensor. ^{Damaged} 85.90 ✓
Tailgate opener Switch. ^{Damaged} 125.50 ✓
Rear Video Recorder. ^{Damaged} ~~500(SN)~~ 420(SN)
Rear LH Fender Air Vent. ^{Distorted} 68.90 ✓

1547.10 SN: 700
1237.68.

To Replace rear video recorder.

~~100~~ . 50

To remove roof upholstery

~~200~~ 120. 170

Supplementary, 2107.68.

\$ 2,727.10